

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 22S RANGE 12W SEC. 4 PLSS # 300700

Date: 9/4/25 By: ke  
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 9-3-25

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS 67/61-20

Corner Designation

Sec Cor  $\frac{32}{5} / \frac{33}{4}$  T21S  
T22S

DOUGLAS COUNTY  
SURVEYOR

Monument(s) Found: (Condition and Source)

3 1/2" Alum Cap on Iron  
Rod 10" Below Surface  
of Rock Road

\_\_\_ Condition report

\_\_\_ Not Found

Renewed

\_\_\_ Unrecorded

\_\_\_ Surveyed In

Previous Renewals

Blachley 1986 M 102-71

MONUMENT DETAIL

T21S R12W

$\frac{S32}{SS} / \frac{S33}{S4}$

RLS 2168  
1986

Accessories Found

Rotted 34" x 4' Sitka Spruce N46°E 90.4  
FT Scribe "B" Visible  
PARTIAL BARK Shell D. FIR S68°E  
33.7 FT

20" x 5 FT D. FIR Stump S54°W 81.7 FT  
Scribes "BT" Visible

30" x 3 1/2' FT Sitka Spruce Stump N49°W  
77.2 FT BLAZE GONE

New Accessories

15" D. FIR N58°E 32.6 FT Scribed  
T21S R12W S33 BT ON Double Blaze

5/8" X 30" Iron Rod with DCSO Plastic  
Cap N42°E 23.1 FT Proj. 1"

5/8" X 30" Iron Rod S54°W 22.8 FT with  
DCSO Plastic Cap Proj. 4"

5/8" X 30" Iron Rod with DCSO Plastic  
Cap N10°W 13.4 FT Proj 12"

Sketch of Monument, Accessories, and General Area

Location & Comments

OCRS Cottage Grove  
Canyonville Location

Mon is buried  
Just to side  
North Road  
Shoulder

43°41'49.71199 N  
124°08'38.36637 W

Comp. Decline. 14°E  
Agency DCSO  
Party Chief S. A. Huse  
Note keeper  
Witnesses J. Loring

CS 67161-20

pg 2/3

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Ronald A. Quimby*

OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1654

EXPIRES: 12/31/2026

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5; 32 & 33 of T21-12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description OCCRS CANYONVILLE (OTTAGE GROVE POSITION) (NOT MM QUALITY)  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description 43°41'49.71199" N  
124°08'38.36637" W

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 3 Page(s) 1262)

-----

Set post cor. of secs. 4, 5, 32 and 33, from which  
 A Spruce 24" dia., bears N.60°W., 16 lks. dist.  
 A Spruce 20" dia., bears S.63°W., 33 lks. dist.  
 A Hemlock 12" dia., bears N.12°E., 19 lks. dist.  
 A Hemlock 24" dia., bears S.15°E., 23 lks. dist.

DECLINATION 14 1/2°E RENEWED 9/3/25

Survey by Andrew T. Blachley - For: Cole & Hongell Logging and International Paper Co. - Oct. 1986 - M 102-71

-----

Did not find original evidence. 3 3/4" ALUMINUM  
 Set by single proportion: 18" ~~STEEL~~ rod with cap mkd: "T21S R12W S32 S33 T22S S5 S4V, 8 1/10" below surface of rock road.

ALSO MARKED "RLS 2168" AND "1986"

New Accessories:  
~~34" x 4 3/8" Sitka Spruce N.46°E., 90.4 ft. mkd. T21S R12W S33 BT~~ ONLY SCRIBED "B" REMAINS  
~~24" D. Fir S.68 1/2°E., 33.7 ft. mkd. T22S R12W S4 BT.~~ BLZ. GONE  
~~20" x 5 FT. 19" D. Fir S.54°W., 81.7 ft. mkd. T22S R12W S5 BT.~~ ONLY SCRIBED "BT" REMAINS  
~~30" x 3 1/2 FT. 28" Sitka Spruce N.49°W., 77.2 ft. mkd. T21S R12W S32 BT~~ BLZ. GONE

Inlet of corrugated metal culvert bears S.54°W., 18 ft. NO EVIDENCE OF INLET, POSSIBLY SOME BURIED METAL

NEW REFS

A 15" DIA. D. FIR SCRIBED "T21S R12W S33" "BT" ON A DOUBLE BLZ.; BEARS N58°E, 32 6/10 FT.

A 5/8" x 30" I.R./DCSO PLSTC. CAP SET PROT. 1" ABOVE GROUND; BEARS N42°E, 23 1/2 FT. DIST.

" " " 4" " ; BEARS S54°W, 22 8/10 FT. DIST.

" " " 12" " ; BEARS N10°W, 13 1/2 FT. DIST.

MONUMENT IS BURIED JUST INSIDE NORTH ROAD SHOULDER.