GOVERNMENT CORNER RESTORATION FORM

FILED
Date: 9-22-25 By: KC
This survey consists of:
Map:
Narrative:
Corner Rpt: CS 67/61-22
DOUGLAS COUNTY SURVEYOR

TOWNSHIP 22S RANGE 13W SEC. 13 PLSS # 600440

DOUGLAS COUNTY OREGON DATE 9-5-25

Corner Designation

1/4 COR S14/S13

Monument(s) Found: (Condition and Source)

3 1/4" BLM BRASS CAP
Flush with ground

Previous Renewals

Hollingsworth 1977 CS 58/152 AND M 66-64
BLM Resurvey 1982 V0144 pg 17068
DCSO 1988 CS 62/49
DCSO 2004 CS 67/6-12B
Heimburger 2014 M 168-25

__ Condition report
__ Not Found
✓ Renewed
__ Unrecorded
__ Surveyed In

MONUMENT DETAIL

T22S R13W
1/4
S14/S13
1982

Accessories Found

11" Spruce N55 1/2° W 32.6FT Fully Healed Double Blaze ADD 3 1/2" Mag Nail Right Side Center
10" Spruce S 10°E 12.0FT Fully Healed Double Blaze ADD 3 1/2" Mag Nail Right Side Center
Steel Post with white paddle Sign S49°E 1.7FT
5/8" Iron Rod S 12°15W 141.6FT No Cap Flush with Ground
Boat Spike in Edge of Road S28° 54' 33"E 169.44 FT Top 2" Bend North

pg 1/3

C.S. File CS 67/61-22

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

Sketch of Monument, Accessories, and General Area

OCRS Cottage Grove - Canyonville Zone Location

43°39'40.92219"N

124°12'13.34246W

Location & Comments

Comp. Decline. 14½° E

Agency DCSO

Party Chief S. Klause

Note keeper

Witnesses J. Corsung

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXPIRES: 12/31/2026

CS 07/01-22

pg 2/3

TOWNSHIP 22 RANGE 13 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias _____ Description OCRS CANONVILLE COTTAGE GROVE POSITION
Alias _____ Description _____
Alias _____ Description 43°39'40.92219"N
Alias _____ Description _____
124°12'13.34246"W

Nail with round head and a 2" shiner in AC now covered by an AC overlay, nail located with metal detector (not uncovered), bears N.71½°E., 178.17 ft., agrees with record.

Coast Guard telephone pole with PK nail on West side 4 ft. above ground now pole cut down and remainder protrudes 5 ft. above ground, bears S.3½°E., 189.57 ft. agrees with record.

Steel post with white paddle bears S.49°E., 1.7 ft. (Rec. East, 2 ft.) (1977)

OSHD station "Guard 1968" has a record bearing and distance of N.57°51'E., 23.73 chains. Station Guard is OK, bearing and distances not checked.

New BTs -5" Spruce double blazed and scribed "¼ S14 CS BT" bears N.55½°W., 32.6 ft.

6" Spruce double blazed and scribed "¼ S13 CS BT" bears S.10°E., 12.0 ft.

Perpetuated as point. Projected by Hollingsworth and accepted by BLM for corner location.

DECLINATION 14 1/2°E RENEWED 9/5/25

FD ok by Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 3/31/2004 - C.S. File 67/6-12B

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 2/19/2007 - C.S. File 67/21-20

Found - 1983 BLM 3¼" dia., brass cap (properly mkd) on 2¼" IP projecting ~~6" above ground~~. NOW FLUSH WITH GRND.

11" ~~5"~~ now ~~9"~~ spruce, fully healed double blaze, bears N.55½°W, 32.6 ft. (agrees w/rec) 1988 BT AND 3½ MAG NAIL R.S.C. TO BOTH 13, T.S. AT RECORD DIST.

10" ~~6"~~ now ~~9"~~ spruce, fully healed double blaze, bears S.10°E. 12.0 ft. (agrees w/rec) 1988 BT

Steel post w/white paddle sign bears S.49°E, 1.7 ft. agrees w/rec.

No other accessories looked for.

New - 5/8" dia., x60" long iron rod, no cap, bears S.12°15'W, 141.61 ft. TOP FLUSH WITH GROUND

Boat spike in edge of rd, ~~driven flush~~, bears S.28°54'33"E., 169.44 ft TO PLUMB PORTION, TOP 2 INCHES BENT NORTH

Basis of bearing back sight staff compass. See sketch of referenced corner in file.

Note - Located Northwesterly of intersection of Salmon Harbor Dr. & Beach Access Rd.

Additional accessories were added because corner was in danger of being destroyed due to construction of new campground to the North

Fd. BC by M Heimburger, 4/2014 - M168-25

CS 67/61-22 pg 3/3