

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 25S RANGE 2W SEC. 32 PLSS # 240100

Date: 9-24-25 By: KL  
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 9-23-25

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS 67161-26

DOUGLAS COUNTY  
SURVEYOR

Corner Designation

1/4 COR SEC 32 ONLY

Monument(s) Found: (Condition and Source)

3 1/4" BLM BRASS CAP  
Proj 12"

Condition report

Not Found

Renewed

Unrecorded

Surveyed In

Previous Renewals

Husford 1960 CS 51/144  
BLM Resurvey 1972-1975  
Vol 36 pg 15106

MONUMENT DETAIL

T25S R2W

1/4 S32

1972

Accessories Found

BURNED Rotted Root Crown out of  
POSITION N. 40 W 13.2 FT TO Roothole

1 1/4" IRON PIPE ON EAST EDGE OF BRASS  
CAP Proj. 11"

New Accessories

BURNED DEAD 8" MADRONE N52°E 7.4 FT

3 1/2" MAG NAIL RIGHT SIDE CENTER

BURNED DEAD 19" D. FIR N33°W 4.9 FT

3 1/2" MAG NAIL RIGHT SIDE CENTER

5/8" X 30" IRON ROD WITH DCSO PLASTIC CAP S11°W 72.5 FT PROJ 6" IN NORTH SHOULDER OF GRAVEL ROAD

5/8" X 30" IRON ROD WITH DCSO PLASTIC CAP S11°W 92.6 FT PROJ 4" IN SOUTH SHOULDER GRAVEL ROAD

Sketch of Monument, Accessories, and General Area

Location & Comments

OCCS Cottage Grove  
CANYONVILLE LOCATION

43°20'37.63520 N

122°57'47.02176 W

AREA Badly Burnt

9/2020

MON ON Steep  
South Slope in  
Burnt Forest Above  
AND APPROX 75% N.  
OF GRAVEL ROAD

Comp. Decline. 14 1/4° E

Agency DCSO

Party Chief S. FRAUSE

Note keeper

Witnesses J. LORSUNG

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Ronald A. Quimby

OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1654

EXPIRES: 12/31/2026

CS 67161-26 pg 2/3

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 32 only

Alias _____	Description _____
Alias _____	Description <u>OCRS CANYONVILLE COTTAGE GROVE PDS.</u>
Alias _____	Description _____
Alias _____	Description <u>43°20'37.63520"N</u>
	<u>122°57'47.02176"W</u>

V.W. Hosford - For: Evans Products Co. - Feb/oct. 1960 - C.S. File 51/144

At 451.2 ft., S.89°55'W, from No. 1/4 cor. of sec. 5, I drove a 1p" Iron pipe 36" long, 12" above the ground, for the South 1/4 cor. of sec. 32, T25S R2W., from which

8" Madrone bears N.70 1/2°W., 11.4 ft. mkd. S 1/4 S32 253 BT, in bark.

8" Madrone bears N.4°W., 12.5 ft. mkd. S 1/4 S32 253 BT, in bark.

DECLINATION 14 1/4°E

RENEWED 9/23/25

BLM Resurvey by Daniel Berry; Harvey Wofford; G. Steven Popken, Cadastral Surveyors, under Group #'s 786, 848 and 854. And Glenn S. Baughman, L.S. #536, under Contract #52500-CT5-1116, Surveyed July 1972/Oct. 1975 - (DCSO records Vol. 36 Page(s) 15106)

The 1/4 sec.cor. of 32 only, established by Hosford in 1960, monumented with an iron pipe, 1 1/2" dia., firmly set, protruding 12" above ground, from which bearing trees mkd. by Hosford:

BURNED AWAY NO EVID. A Madrone 8" dia., bears N.72°W., 18 lks. dist., with scribe marks S 1/4 S32 253 BT visible on bark blaze.

BURNED ROTTED ROOT CROWN, OUT OF PDS - A Madrone 10" dia., bears N.6°W. 20 lks. dist., with scribe marks S 1/4 S32 253 BT visible on bark blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: 3 1/4" B.C. 1/4 S 32 ✓ PROT. 12"

1 1/4" I.D.

1972

Deposit the iron pipe ✓ alongside the iron post. ON EAST EDGE OF B.C. PROT. 11"

NEW REFERENCES

A BURNED DEAD 8" DIAM. MADRONE WITH A 3 1/2" MAG NAIL R.S.C.

BEARS N52°E, 7 1/4 FT. DISTANT

A 5/8" x 30" I.R./DCSO PLSTC. CAP SET PROT. 6" IN NORTH SHLD. GRAVEL RD.

BEARS S11°W, 72 1/2 FT. DISTANT

" " " PROT. 4" IN SOUTH SHLD. GRAVEL RD.

BEARS S11°W, 92 1/2 FT. DISTANT

A BURNED DEAD 19" DIAM. D. FIR WITH A 3 1/2" MAG NAIL R.S.C.

BEARS N33°W, 49 FT. DISTANT

MON. ON STEEP SOUTH SLOPE IN BURNED FOREST ABOVE AND

APPROX. 75 FT NORTH FROM GRAVEL RD. CS 67101-26 PG 3/3