

TOWNSHIP 26S RANGE 2W SEC. 18 PLSS # 140400

Date: 11/12/25 By: KE  
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 10-28-25

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS 67161-36

Corner Designation

5/4 S 18 only

DOUGLAS COUNTY  
SURVEYOR

Monument(s) Found: (Condition and Source)

\_\_\_ Condition report

GLO BRASS CAP ON

\_\_\_ Not Found

Iron Pipe proj 2"

\_\_\_ Renewed

\_\_\_ Unrecorded

Previous Renewals

\_\_\_ Surveyed In

GLO Resurvey 1916-1918

Vol 10 Pg 4319

Williams 1976 & 2016 CS 59/46-12

DCSO 1978 CS 59/46-11

BLM Resurvey 2015 Vol 58

Pg 23487 Plat T26-2 2017-1

MONUMENT DETAIL

1/4 S 18  
1918

Accessories Found

23" X 20 FT FIR SNA9 N47°E 11.4 FT

ADD 3 1/2" MAG NAIL RIGHT SIDE CENTER

Burnt 49" FIR SNA9 S29°W 27.8 FT Healed

BLAZE Add 3 1/2" MAG NAIL RIGHT SIDE CENTER

Burnt 28" FIR SNA9 S77 1/2°E 41.3 FT Healed

BLAZE A 3 1/2" MAG NAIL RIGHT SIDE CENTER

BLM BRASS CAP Reference Monument

S47°32'43"W 53.20 FT Stamped RM2 519 53.2 FT

To Cor 2015 ARROW pointing To Corner

BLM BRASS CAP Reference Monument

N16°32'50"W 26.20 FT Stamped RM 1 1/4 S 18

26.2 FT To Cor 2015 ARROW pointing To

Corner

Alum. Angle Iron 0.6 FT EAST OF

Monument

Monument Set (Procedure and Description)

MONUMENT DETAIL

Horizontal lines for Monument Set description.

New Accessories

Horizontal lines for New Accessories description.

Sketch of Monument, Accessories, and General Area

Location & Comments

LAT. 43°17'57.084 N  
LONG 122°58'53.34 W

MAP ON Steep  
Rocky EAST Slope  
Burnt & Cleared  
Approx 220 FT x E  
ACCESS ROAD  
AREA Burnt  
9/2020

Comp. Decline. 14'14"E  
Agency DCSO  
Party Chief J. Loring  
Note keeper  
Witnesses

CS 67/61-34  
pg 2/4

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Ronald A. Quimby*

OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1654

EXPIRES: 12/31/2026

PRIMARY CORNER DESCRIPTION South 1/4 Cor. Sec 18 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Gary Langlitz - Stephen Flause  
- March 4, 1978 - C.S. File 59/46-11

- 
- Found - A 1" I.P. extending ~~14"~~<sup>21"</sup> above ground on a steep easterly slope, with a 1918 GLO brass cap.  
An orig. 36" D.Fir now 32" alive, but in poor condition, no scribing visible on rotten face, bears N.47°E., 11.2 ft.  
An orig. 18" D.Fir now a 25" stump with well healed blaze bears N.20°W., 38.3 ft. "W-Nail" in base of this BT bears N.20°W., 37.0 ft (1918 resurvey)  
A "W-Nail" in the base of a 44" D.Fir bears S.33°W. 25.7 ft
- Set - At the present position of the 1918 GLO monument, we lower said monument to extend approx 3/4 inches above ground.
- New - An 18" D.Fir scribed "RP S ¼ S18 CS BT" on a double blaze, bears S.77°E., 40.3 ft.
- Note - Corner located along southerly edge of recently logged area.

BLM dependent resurvey by Joel R Herzberg, Cadastral Surveyor under Group No. 2817, surveyed Oct./Nov. 2015 - (DCSO records Vol. 58 Page(s) 23487 & Plat T26-2 2017-1)

-----  
The ¼ sec. cor. of sec. 18 only, perpetuated by the Douglas County Surveyor's Office in March of 1978, monumented with an iron pipe, 1" dia., firmly set, projecting 2" above the ground, with brass cap (properly) mkd.

23" x 20 FT - A burnt fir snag, size indeterminate, bears N.47°E., 11.2 ft., with illegible scribe marks visible on an open blaze.

gone - A burnt fir stump, size indeterminate, bears N.20°W., 38.3 ft., with no marks visible and a spike in the stump facing the cor.

and the remains of a BT mkd. by persons unknown, reported by the Douglas County Surveyor's Office

A burnt fir snag, ~~53"~~<sup>8"</sup> dia., bears S.29°W., 27.6 ft., with a healed blaze. 49"

and the remains of a BT mkd by the Douglas Co. Surveyor's Office

A burnt fir snag, 33" dia., bears S.77½°E., 41.3 ft., with a healed blaze. 28"

and new reference monuments

A stainless steel post, 28" long, 2½" dia., set 26" in the ground for a reference monument, bears S.47°32'43"W, 53.20 ft., with brass cap mkd. RM2 S19 53.2 FT TO COR 2015 and an arrow pointing to the cor. Build mound of stone, 2 ft. base, 1 ft. high, and drive an alum angle iron, 5 ft. long, alongside the stainless steel post. continued next page

gone

CS 07/01-36

pg 3/4

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 140400

PRIMARY CORNER DESCRIPTION South 1/4 Cor. Sec 18 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A stainless steel post, 28" long, 2½" dia., set 26" in the ground for a reference monument, bears N.16°32'50"W., 26.20 ft., with brass cap mkd. RM ¼ S18 26.2 FT TO COR 2015 and an arrow pointing to the cor.

Drive an aluminum angle iron, 5 ft. long, alongside the cor.

**Note:** The source document for the perpetuation of this cor. by the Douglas County Surveyor's Office is CS 59/46. This document could not be found in the County Surveyor's Office at the time of this survey. The Douglas County Surveyor's Office Corner Renewal Index 140400 was utilized for the information for this cor. (Added 9/26/2017 See C.S. 59/46-11)

FOUND ALUMINUM ANGLE IRON .6 FT EAST OF CORNER. CORNER LIES ON STEEP ROCKY EAST SLOPE, BURNED + CLEARCUT. Approx 270 FT WEST OF ACCESS ROAD.

OCSRS WOULD NOT GET BELOW 20 FT. DUE TO TERRAIN.

LAT: 43° 17' 57.084" N, LONG: 122° 58' 53.364" W

ALL TREES TAGGED + SIDE SPIKED.

CS 67/61-26 pg 4/4