

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 26S RANGE BW SEC. 9

PLSS # 400528

Date: 4/8/20 By: ke
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 3-31-26

Map: _____
Narrative: _____
Corner Rpt: CS 67/02-35

Corner Designation

SEC COR 9/10
16/15

DOUGLAS COUNTY
SURVEYOR

Monument(s) Found: (Condition and Source)

BLM BRASS CAP, Projecting
6"

- Condition report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

Previous Renewals

GLO Survey 1896 Vol 11 pg 4717
Weyerhaeuser 1970 CS 55/155A
BLM Resurvey 1977 Vol 40 pg
15953

MONUMENT DETAIL

T26S RBW
59/510
516/515
1977

Accessories Found

25" x 4 FT SAWN CORNER STUMP S43 1/2° W 35.2 FT
(Rec S47 1/4° W 55 LKS)

New Accessories

24" X 1 FT SAWN D. FIR STUMP N 16° E
6.5 FT

16" X 3 FT SAWN D. FIR STUMP S 74° E 10.4 FT

15" X 1 FT SAWN D. FIR STUMP S 159° W 17.8 FT

3 New Stump B.O. are spiked with
3 1/2" MAG Nail Top Center

Sketch of Monument, Accessories, and General Area

Location & Comments

CORNER IS 60 FT NORTH
OF LOGGING ROAD ON
NORTH FACING BENCH

TRIMBLE GED XT POSITION

43° 31594394 N
123° 64488733 W

Comp. Decline. 14' 14" E
Agency DCSD
Party Chief J. LORSUNG
Note keeper
Witnesses SP HAUZE

CS 67162-35 pg 24

REGISTERED
PROFESSIONAL
LAND SURVEYOR

R. Quimby

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXPIRES: 12/31/2026

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Cor Secs. 9, 10, 15, & 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

25" x 4 FT
GONE - A sawed cedar stump, 33" dia., bears S.53°E., 10 lks.,
with a nail with "W" embossed on head, at base. ~~352~~
A sawed cedar stump, 28" dia., bears S ~~44~~°W., ~~55~~ lks.,
with a nail with "W" embossed on head, at base.

At the corner point
Set an iron post, 28" long, 2½" dia. 24" in the ground,
directly over iron bolt, with brass cap mkd. ✓

T26S R8W
S 9 | S 10 ✓
S 16 | S 15 ✓
1977

No suitable trees available within limits.

TRIMBLE GEO XT POS: N - 43.31599394°
W - 123.64488733°

NEW BT'S:

- 24" x 1 FT TALL SAWN D. FIR STUMP BEARS, N 16° E
6⁵ FT.
- 16" x 3 FT TALL SAWN D. FIR STUMP BEARS, S 74° E
10⁴ FT.
- 15" x 1 FT TALL SAWN D. FIR STUMP BEARS, S 15° W
17⁸ FT.

CORNER FALLS 60 FT. NORTH OF LOGGING
ROAD ON A SMALL NORTH FACING BENCH. ALL
STUMPS ARE TOP CENTER SPIKED W/ 3½ INCH
MAG NAILS.

DEC - 14¹⁰/₄

CAP PROJECTING 6" PROPERLY MARKED

CS 67/62-35 pg 4/4

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Cor. Secs. 9, 10, 15, & 16

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4678-9)

Set a fir post, 3 ft. long, 4" sq., 24" in the ground for cor. of secs. 9, 10, 15, & 16, mkd T26S S10 on NE, R8W S15 on SE, S16 on SW & S9 on NW faces with 3 notches on E and 4 notches on S edges, from which

A fir, 30" dia. bears N.32°E., 26 lks mkd: T26S R8W S10 BT

A maple, 12" dia., bears S.31°E., 18 lks., mkd: T26S R8W S15 BT.

A maple, 10" dia., bears S.37°W., 36 lks., mkd: T26S R8W S16 BT.

A fir, 36" dia. bears N.83°W., 51 lks. mkd: T26S R8W S9 BT

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4717)

Correction of surveys as ordered by the Commissioner of the GLO under date of March 18, 1898:

The Cor, to Secs. 9, 10, 15 & 16, as reported in orig. notes on file in the US Surveyor General's Office. From this cor. I trace without re-measuring the surveyed lines & examine each cor, on the W & N bdrs. of the remainder of this tier of Secs. verify the witnesses thereto and where necessary correct markings thereon to correspond with notes, now on file in the U S Surveyor Generals Office.

Weyerhaeuser reports received 6/17/1970 - C.S. File 55/155A

12/1968 By Williams BTs, mks, tag

BLM dependent resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #350, surveyed 5/1977 - (DCSO record Vol. 40 Page 15953)

The cor. of secs. 9, 10, 15, & 16, perpetuated & recorded by Robert C. Adamek, Reg. Land Surveyor No. 999, in 1974, for Weyerhaeuser Timber Company, (DCSO does not have this survey) monumented with an iron bolt, 3/4" dia., firmly set, projecting 6", above ground, from which the remains of the orig. BTs:

ROTTED SMAG - A sawed fir stump, 34" dia., bears N.32°E., 26 lks., no marks visible.

ROTTED SMAG - A sawed fir stump, 50" dia., bears N.83°W., 51 lks., with scribe marks T26S R visible on bark blaze. and the remains of bearing trees mid, by Adamek continued next page