

Station: BEND


T 26 S, R 6W, Sec 19

Date Set: 11/02/98

Set By (Agency): DCSO


Date Recovered: 11/02/98

Recovered By: RWS, SJF



B-150

- Found
- New
- Reset
- Not Found
- Referenced
- Destroyed



VERTICAL CONTROL

Elevation: 381.07 NGS Line # _____ USGS Line # _____ OSHD Line # _____

Precision: 3rd Agency: DCSO Proj. # 2007 Date: 1998

HORIZONTAL CONTROL CORPSCONG NAVD88 384.53 FT. CS File # 66/020

South Zone O.C.S. 27: Y(Northing) _____ X(Easting) _____

South Zone O.C.S. 83: Y(Northing) 606374 X(Easting) 4135579

Precision: GIS SCALED Agency: DCSO Proj. # _____ Date: 2014

Approx. NAD 83 Geographic Position: Latitude _____ Longitude _____

DESCRIPTION and TO REACH

0.3 Mi Rb 220

A 2 INCH DIAMETER BRASS DISK STAMPED "BEND 1998"
SET IN QUICK-SET CONCRETE IN TOP OF ROUGH CONCRETE
CULVERT HEADWALL AT NORTH EDGE OF ROAD.

FROM THE INTERSECTION OF GARDEN VALLEY ROAD (Co. Rd. #6) AND
BIG BEND ROAD (Co. Rd. #220) IN T26S, R6W, SEC 19 PROCEED WESTERLY
ALONG BIG BEND ROAD APPROX. 0.3 MI TO MONUMENT ON RIGHT.

Reference Marks:

