


OFFICE OF THE
DOUGLAS COUNTY SURVEYOR
B-152



Station: BECK T 22 S, R 7W, Sec 30


Date Set: 1998 (MARKED)

Set By (Agency): DCSO (MARKED)

Date Recovered: 10/12/98

Recovered By: RWS, SJF

- Found
- New
- Reset
- Not Found
- Referenced
- Destroyed



VERTICAL CONTROL

Elevation: 137.95 FT. NGS Line # _____ USGS Line # _____ OSHD Line # _____

Precision: 3RD. Agency: DCSO Proj. # 2007 Date: 1998

HORIZONTAL CONTROL

South Zone O.C.S. 27: Y(Northing) _____ X(Easting) _____

South Zone O.C.S. 83: Y(Northing) 731105 X(Easting) 4109902

Precision: GIS SCALED Agency: DCSO Proj. # _____ Date: 2014

Approx. NAD 83 Geographic Position: Latitude 43° 37' 55" Longitude 123° 33' 51"

DESCRIPTION and TO REACH

A FOUND 2 7/8 INCH DIAMETER UNMARKED DISK, NOW STAMPED "DCSO BECK 1998" SET FLUSH IN CONCRETE CURBING OF CONCRETE BRIDGE SPANNING THE UMPQUA RIVER.

FROM THE INTERSECTION STATE HIGHWAY 138 AND MEHL CREEK ROAD (Co.Rd.#11) IN T22S, R7W, SEC. 29 PROCEED WESTERLY ALONG MEHL CREEK ROAD TO THE EAST END OF THE MARY BECKLEY BRIDGE STRUCTURE AND THE MONUMENT ON THE LEFT.

Reference Marks:

