


OFFICE OF THE
DOUGLAS COUNTY SURVEYOR


B-158



Station: BENEDICT
Date Set: 1998
Set By (Agency): DCSO
Date Recovered: 12-17-98
Recovered By: RWS SJF

T 29 S, R 7W, Sec 6

- Found
- New
- Reset
- Not Found
- Referenced
- Destroyed



B-158

VERTICAL CONTROL CORPSCON6 NAVDBB 892.28 FT.

Elevation: 888.85 NGS Line # _____ USGS Line # _____ OSHD Line # _____

Precision: 3rd Agency: DCSO Proj. # 2007 Date: 1998

HORIZONTAL CONTROL

CS66/50

South Zone O.C.S. 27: Y(Northing) _____ X(Easting) _____

South Zone O.C.S. 83: Y(Northing) 528141 X(Easting) 4101644

Precision: GIS SCALED Agency: DCSO Proj. # _____ Date: 2014

Approx. NAD ⁸³/₂₇ Geographic Position: Latitude 43° 04' 29" Longitude 123° 34' 02"

DESCRIPTION and TO REACH

DCSO BRASS CAP SET IN ROCK OUTCROP STAMPED
"BENEDICT 1998"

FROM THE INTERSECTION OF STATE HWY #2 AND
BENEDICT ROAD (CO. RD #141) IN T29S R7W SEC 6
PROCEED SOUTHERLY ALONG BENEDICT ROAD
0.8 MILES TO MONUMENT ON LEFT.

4101644.53
528141.82

Reference Marks:

