



OFFICE OF THE
DOUGLAS COUNTY SURVEYOR
D-089



Station: DAHLIA
Date Set: 1998
Set By (Agency): DCSO
Date Recovered: _____
Recovered By: RWS, SJF

T 26 S, R 6W, Sec 19



- Found New
 Reset Not Found
 Referenced Destroyed

VERTICAL CONTROL NGVD 29

Elevation: 3851.20
Precision: 3rd

CORPSON 6 NAVD 88 388.66 FT
NGS Line # _____ USGS Line # _____ OSHD Line # _____

HORIZONTAL CONTROL

South Zone O.C.S. 27: Y(Northing) _____ X(Easting) _____
South Zone O.C.S. 83: Y(Northing) _____ X(Easting) _____
Precision: _____ Agency: _____ Proj. # _____ Date: _____
Approx. NAD 83 Geographic Position: Latitude _____ Longitude _____

DESCRIPTION and TO REACH

A 3 INCH DIAMETER DCSO DRILL CAP STAMPED "DAHLIA 1998" SET FLUSH IN TOP AND NEAR SOUTH END OF AN APPROXIMATELY 3x7 FOOT BOULDER OF INDETERMINATE DEPTH WHICH LIES MOSTLY BURIED IN ROADWAY FILLBANK.

MONUMENT LIES JUST SOUTH OF INTERSECTION OF GARDEN VALLEY ROAD (Co. RD. #6) AND LOWER GARDEN VALLEY ROAD (Co. RD. #191) IN T26S, R6W, SEC.19. MONUMENT IS SLIGHTLY LOWER THAN AND WEST OF GARDEN VALLEY ROAD WEST SHOULDER.

Reference Marks:

