


# DOUGLAS COUNTY SURVEYOR'S OFFICE

Designation: D-093 Station: DRAIN-1 T 22S R 5W S 17  $\frac{1}{4}$  NW

Date Set: 8-8-00 Set by (Agency): DCSO

Date Recovered: 8-8-00 Recovered by: RWS SJF

- |                                    |   |                                    |
|------------------------------------|---|------------------------------------|
| <input type="checkbox"/> Found     | <input checked="" type="checkbox"/> New | <input type="checkbox"/> Reset     |
| <input type="checkbox"/> Not Found | <input type="checkbox"/> Referenced     | <input type="checkbox"/> Destroyed |



### VERTICAL CONTROL

NGVD 29 Elevation: 286.21 Feet File # CS66/024

Precision: 3rd Agency: DCSO Project: 2007 Date: 2000

NAVD 88 Elevation: 289.82 <sup>FEET</sup> ~~Meters~~ File # \_\_\_\_\_

Precision: CORPSCON 6 Agency: \_\_\_\_\_ Project: \_\_\_\_\_ Date: \_\_\_\_\_

### HORIZONTAL CONTROL - south zone

N \_\_\_\_\_ E \_\_\_\_\_ Datum/Adj.: 1927 Precision: GIS

Lat: 43° 39' 37.0 Long: 123° 19' 23.2 Agency: DCSO File # CS66/024 Date: 2000

N \_\_\_\_\_ E \_\_\_\_\_ Datum/Adj.: 83 Precision: GIS

Lat: 43° 39' 36.5 Long: 123° 19' 27.6 Agency: DCSO File # CS66/024 Date: 2000

N \_\_\_\_\_ E \_\_\_\_\_ Datum/Adj.: \_\_\_\_\_ Precision: \_\_\_\_\_

Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Agency: \_\_\_\_\_ File # \_\_\_\_\_ Date: \_\_\_\_\_

N \_\_\_\_\_ E \_\_\_\_\_ Datum/Adj.: \_\_\_\_\_ Precision: \_\_\_\_\_

Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Agency: \_\_\_\_\_ File # \_\_\_\_\_ Date: \_\_\_\_\_

### DESCRIPTION AND TO REACH

DCSO DRILL CAP STAMPED  
"DRAIN-1 2000" SET IN  
CONCRETE CURB OF OLD  
SEWER PLANT ACCESS SIDEWALK

FROM THE INTERSECTION OF  
CEDAR ST. AND DIVISION AVE.  
IN DRAIN, PROCEED WESTWARDLY  
ALONG DIVISION AVE.  
0.35 MILES TO MONUMENT  
ON LEFT.

