

**DOUGLAS COUNTY SURVEYOR'S OFFICE**

Designation: G-029 Station: GLEND A T 26S R 6W S 25 1/4 SE

Date Set: 1983 Set by (Agency): DCSO

Date Recovered: 2/28/08 Recovered by: SJF, JAP

- |   |                                     |                                    |
|---|-------------------------------------|------------------------------------|
| <input checked="" type="checkbox"/> Found | <input type="checkbox"/> New        | <input type="checkbox"/> Reset     |
| <input type="checkbox"/> Not Found        | <input type="checkbox"/> Referenced | <input type="checkbox"/> Destroyed |




PHOTO  
#100-1324

**VERTICAL CONTROL**

NGVD 29 Elevation: 478.60 Feet File # \_\_\_\_\_

Precision: 3M Agency: DCPW Project: \_\_\_\_\_ Date: 2003

NAVD 88 Elevation: 482.09 <sup>FEET</sup> ~~Meters~~ File # \_\_\_\_\_

Precision: CORPSON 6 Agency: \_\_\_\_\_ Project: \_\_\_\_\_ Date: \_\_\_\_\_

**HORIZONTAL CONTROL - south zone**

N 598,405.55 E 4,161,583.56 Datum/Adj.: NAD83-FT Precision: AERIAL PLOT

Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Agency: \_\_\_\_\_ File # \_\_\_\_\_ Date: \_\_\_\_\_

N \_\_\_\_\_ E \_\_\_\_\_ Datum/Adj.: \_\_\_\_\_ Precision: \_\_\_\_\_

Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Agency: \_\_\_\_\_ File # \_\_\_\_\_ Date: \_\_\_\_\_

N \_\_\_\_\_ E \_\_\_\_\_ Datum/Adj.: \_\_\_\_\_ Precision: \_\_\_\_\_

Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Agency: \_\_\_\_\_ File # \_\_\_\_\_ Date: \_\_\_\_\_

N \_\_\_\_\_ E \_\_\_\_\_ Datum/Adj.: \_\_\_\_\_ Precision: \_\_\_\_\_

Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Agency: \_\_\_\_\_ File # \_\_\_\_\_ Date: \_\_\_\_\_

**DESCRIPTION AND TO REACH**

ADCSO DISK STAMPED  
"GLEND A 1983" SET FLUSH  
IN CONCRETE CURB.

GO TO THE INTERSECTION  
OF HWY 99 AND GLEND A  
AVENUE IN T26S R6W SEC 25.

\* NOTE: CURB IS CRACKED  
DCPW 2003 ELEVATION  
REFLECTS ELEVATION  
CHANGE.

