


DOUGLAS COUNTY SURVEYOR'S OFFICE

Designation: L-080 Station: LESLEE TZ15 RSW S36 1/4 A

Date Set: 3-26-98 Set by (Agency): DCSO

Date Recovered: 3-26-98 Recovered by: RWS SJF

- Found New Reset
 Not Found Referenced Destroyed



VERTICAL CONTROL

NGVD 29 Elevation: _____ Feet File # _____

Precision: _____ Agency: _____ Project: _____ Date: _____

NAVD 88 Elevation: _____ Meters File # _____

Precision: _____ Agency: _____ Project: _____ Date: _____

HORIZONTAL CONTROL - south zone

N _____ E _____ Datum/Adj.: 1927 Precision: SCALED

Lat: 43°42'21" Long: 123°14'11" Agency: _____ File # _____ Date: _____

N 754983 E 4197477 Datum/Adj.: 83 Precision: GIS SCALED

Lat: _____ Long: _____ Agency: DCSO File # _____ Date: 2014

N _____ E _____ Datum/Adj.: _____ Precision: _____

Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____

N _____ E _____ Datum/Adj.: _____ Precision: _____

Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____

DESCRIPTION AND TO REACH

SEE NGS WEBSITE

DCSO DRILL CAPSET IN ROCK OUTCROP

FROM THE INTERSECTION OF I-5 AND
ST. HWY 38 (EXIT 162) PROCEED
WESTERLY TOWARDS DRAIN ALONG
HWY 38 1.0 MILE TO LARGE
ROCK CUT BANK ON RIGHT
STATION IS ON THE LEFT.

