



OFFICE OF THE
DOUGLAS COUNTY SURVEYOR

Station: M83
 Date Set: 1991
 Set By (Agency): City of M.C.
 Date Recovered: 10/16/91
 Recovered By: Ruppert LS 866
 Date Recovered: _____
 Recovered By: _____
 Date Recovered: _____
 Recovered By: _____

T 29 S, R 5W , Sec 28



M-083
M83
29S 5W 28
 NAD 507327.81 4175241.15
 83 43° 1'29" 123°17'26"



VERTICAL CONTROL **NGVD29**

Elevation: 603.1 NGS Line # _____ USGS Line # _____ OSHD Line # _____
 Precision: GPS Agency: DCSO Proj. # 2017-1 CS 64/22 Date: 1991

HORIZONTAL CONTROL


South Zone O.C.S. 27: Y(Northing) 507,363.39 X(Easting) 1,254,282.70
 South Zone O.C.S. 83: Y(Northing) _____ X(Easting) _____
 Precision: 1/15,000 Agency: DCSO Proj. # 2017-1 CS 64/22 Date: 1991
 Approx. NAD 83 Geographic Position: Latitude _____ Longitude _____

DESCRIPTION and TO REACH

SET: A standard DCSO disk stamped "M83 1991"
set in planter curb.

To Reach: At the intersection of Volunteer Way and
2nd Ave. in Myrtle Creek.

SKETCH



Reference Marks:

Note: For further information, contact the Douglas County Surveyor's Office, Room 205 Douglas County Justice Building, Roseburg, OR 97470. Phone 440-4278. Douglas County residents outside the Roseburg calling area, dial toll free 1-800-452-0991.