


OFFICE OF THE
DOUGLAS COUNTY SURVEYOR


Station: RAYMER
Date Set: 1999
Set By (Agency): DCSO
Date Recovered: 5/20/99
Recovered By: RWS, SJF

T 26 S, R 4W, Sec 17



R-107

- Found New
 Reset Not Found
 Referenced Destroyed



VERTICAL CONTROL

Elevation: 660.82 NGS Line # _____ USGS Line # _____ OSHD Line # _____
Precision: 3rd Agency: DCSO Proj. # 2007 Date: 1999

HORIZONTAL CONTROL CORPSCON6 NAVDBB 664.36 FT. CS66/37

South Zone O.C.S. 27: Y(Northing) _____ X(Easting) _____

South Zone O.C.S. 83: Y(Northing) 611205 X(Easting) 4201832

Precision: GIS SCALED Agency: DCSO Proj. # _____ Date: 2014

Approx. NAD 83 Geographic Position: Latitude 43° 18' 43" Longitude 123° 12' 11"

DESCRIPTION and TO REACH

A 3 INCH DIAMETER DCSO DRILL CAP STAMPED "RAYMER 1999" SET FLUSH IN TOP, AND NEAR SOUTHEASTLY END, OF 24 INCH O.D. CONCRETE CULVERT.

FROM THE INTERSECTION OF WHISTLERS LANE (CO. RD. #223) AND WHISTLERS PARK RD. (CO. RD. #244) PROCEED NORTHERLY AND WESTERLY ALONG WHISTLERS PARK ROAD APPROXIMATELY 0.80 MILES TO MONUMENT ON LEFT.

Reference Marks:

