


DOUGLAS COUNTY SURVEYOR'S OFFICE

Designation: R-116 Station: RIDDLE T 30S R 6W S 24 1/4 SW

Date Set: 8-13-2009 Set by (Agency): DCSO

Date Recovered: 8-13-2009 Recovered by: NWS SJF



- Found New Reset
 Not Found Referenced Destroyed

VERTICAL CONTROL

NGVD 29 Elevation: 676.49 Feet File # _____
 Precision: 3rd Agency: DCSO Project: 2007 Date: 2009
 NAVD 88 Elevation: _____ Meters File # _____
 Precision: _____ Agency: _____ Project: _____ Date: _____

HORIZONTAL CONTROL - south zone

N 479578.12 E 4155051.89 Datum/Adj.: NAD 83 Precision: SCALED
 Lat: 42°56'47.2" Long: 123°21'44.6" Agency: _____ File # _____ Date: _____
 N _____ E _____ Datum/Adj.: _____ Precision: _____
 Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____
 N _____ E _____ Datum/Adj.: _____ Precision: _____
 Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____
 N _____ E _____ Datum/Adj.: _____ Precision: _____
 Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____

DESCRIPTION AND TO REACH

DCSO DISK STAMPED "RIDDLE
2009" SET FLUSH IN
SW CORNER RIDDLE
ADJUTMENT.

IN RIDDLE SOUTHWEST
END OF BEARER OVER
COW CREEK.

