


OFFICE OF THE
DOUGLAS COUNTY SURVEYOR

S-183



264
412
2 E
W.P.

Station: SCR-6

T 28 S, R 7, Sec 11


Date Set: 1998

Set By (Agency): DCSO

Date Recovered: 7-27-98

Recovered By: KWS SJF

- Found
- New
- Reset
- Not Found
- Referenced
- Destroyed



VERTICAL CONTROL NGVD 29

Elevation: 621.49 NGS Line # _____ USGS Line # _____ OSHD Line # _____

Precision: 3rd Agency: DCSO Proj. # 2007 Date: 1998

HORIZONTAL CONTROL

South Zone O.C.S. 27: Y(Northing) _____ X(Easting) _____

South Zone O.C.S. 83: Y(Northing) _____ X(Easting) _____

Precision: _____ Agency: _____ Proj. # _____ Date: _____

Approx. NAD ²⁷ Geographic Position: Latitude 43° 08' 41" Longitude 123° 29' 59"

DESCRIPTION and TO REACH

2 3/4" DIA DCSO DRILL CAP STAMPED "SCR-6 1998"
SET IN AN 8" DIA BY 45" LONG CONCRETE
FILLED BELL TILE, PROTRUSORS 8" IN ABOVE GROUND.

FROM THE INTERSECTION OF STATE HWY 60
AND STRICKLAND CANYON ROAD (CO. RD #100)
IN T28S R7W SEC 27, PROCEED NORTHERLY
ALONG STRICKLAND CANYON ROAD 3.7 MILES
TO MONUMENT ON RIGHT.

Reference Marks:

