


# DOUGLAS COUNTY SURVEYOR'S OFFICE

Designation: S-194 Station: SHINE T 26S R 5W S 26 1/4 A

Date Set: 1999 Set by (Agency): DCSO

Date Recovered: 5/2001 Recovered by: RWS SJF

- |   |   |                                    |
|---|---|------------------------------------|
| <input checked="" type="checkbox"/> Found | <input checked="" type="checkbox"/> New | <input type="checkbox"/> Reset     |
| <input type="checkbox"/> Not Found        | <input type="checkbox"/> Referenced     | <input type="checkbox"/> Destroyed |



### VERTICAL CONTROL

NGVD 29 Elevation: 554.80 Feet File # \_\_\_\_\_

Precision: 3rd Agency: DCSO Project: 2007 Date: 2001

NAVD 88 Elevation: 558.33 FT. File # \_\_\_\_\_

Precision: CORPSCON6 NAVDBB Agency: \_\_\_\_\_ Project: \_\_\_\_\_ Date: \_\_\_\_\_

### HORIZONTAL CONTROL - south zone

N: \_\_\_\_\_ E: \_\_\_\_\_ Datum/Adj.: 1927 Precision: SCALED

Lat: 43°17'03" Long: 123°15'19" Agency: \_\_\_\_\_ File # \_\_\_\_\_ Date: \_\_\_\_\_

N 601710 E 4186747 Datum/Adj.: 83 Precision: GIS SCALED

Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Agency: DCSO File # \_\_\_\_\_ Date: 2014

N \_\_\_\_\_ E \_\_\_\_\_ Datum/Adj.: \_\_\_\_\_ Precision: \_\_\_\_\_

Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Agency: \_\_\_\_\_ File # \_\_\_\_\_ Date: \_\_\_\_\_

N \_\_\_\_\_ E \_\_\_\_\_ Datum/Adj.: \_\_\_\_\_ Precision: \_\_\_\_\_

Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Agency: \_\_\_\_\_ File # \_\_\_\_\_ Date: \_\_\_\_\_

### DESCRIPTION AND TO REACH

DCSO DRILL CAP STAMPED

"SHINE 1999" SET IN SOUTH EAST CONCRETE BRIDGE PIER.

FROM THE INTERSECTION OF SUNSHINE ROAD (CO. RD # 3E) AND STILLWATER ROAD (CO. RD 58A) IN T26S R5W SEC 26 PROCEED NORTH WESTERLY ALONG SUNSHINE ROAD (BECOMES RIONES LN) 0.3 MILES TO WOODEN DECKED BRIDGE OVER LOWER CREEK AND ALIGNMENT ON LEFT IN SOUTH EAST CONCRETE BRIDGE PIER.

