


GIS R 021200C **DOUGLAS COUNTY SURVEYOR'S OFFICE**

Designation: S-198 Station: SING-3 T 26 R 6W S 32 ¼ SE

Date Set: 2003 Set by (Agency): DCSO

Date Recovered: 2-10-03 Recovered by: RWS SIF

- Found
- Not Found
- New
- Referenced
- Reset
- Destroyed



VERTICAL CONTROL

NGVD 29 Elevation: 393.23 Feet File # CS66/62  
 Precision: 3rd Agency: DCSO Project: 2007 Date: 2003

NAVD 88 Elevation: \_\_\_\_\_ Meters File # \_\_\_\_\_  
 Precision: \_\_\_\_\_ Agency: \_\_\_\_\_ Project: \_\_\_\_\_ Date: \_\_\_\_\_

HORIZONTAL CONTROL - south zone

N \_\_\_\_\_ E \_\_\_\_\_ Datum/Adj.: 1929 Precision: GIS  
 Lat: 43°15'54.5" Long: 123°25'50.4" Agency: DCSO File # CS66/62 Date: 2003

N \_\_\_\_\_ E \_\_\_\_\_ Datum/Adj.: \_\_\_\_\_ Precision: \_\_\_\_\_  
 Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Agency: \_\_\_\_\_ File # \_\_\_\_\_ Date: \_\_\_\_\_

N \_\_\_\_\_ E \_\_\_\_\_ Datum/Adj.: \_\_\_\_\_ Precision: \_\_\_\_\_  
 Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Agency: \_\_\_\_\_ File # \_\_\_\_\_ Date: \_\_\_\_\_

N \_\_\_\_\_ E \_\_\_\_\_ Datum/Adj.: \_\_\_\_\_ Precision: \_\_\_\_\_  
 Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Agency: \_\_\_\_\_ File # \_\_\_\_\_ Date: \_\_\_\_\_

DESCRIPTION AND TO REACH

DCSO DRILL CAP STAMPED  
"SING-3 2003" SET IN  
TOP OF 36" DIA CONCRETE  
DRAIN CULVERT  
FROM THE INTERSECTION  
OF QUAIL LN (CO. RD #138)  
AND GARDEN VALLEY RD  
(CO. RD #6) IN T 26 S R 6 W  
SECTION 32 PROCEED  
WESTWARD ALONG QUAIL LN  
1.15 MILE TO MONUMENT  
ON LEFT

