


DOUGLAS COUNTY SURVEYOR'S OFFICE

Designation: W-012 Station: WILLIS RM 1 T 29S R 6W S 3 1/4 B

Date Set: 1985 Set by (Agency): DCSO

Date Recovered: OCT. 2003 Recovered by: SJF, JAP

- Found New Reset
 Not Found Referenced Destroyed



VERTICAL CONTROL

NGVD 29 Elevation: 538.88 Feet File # CS 66/55
 Precision: 3RD. ORDER Agency: DCSO Project: _____ Date: 2000
 NAVD 88 Elevation: _____ Meters File # CS 66/55
 Precision: _____ Agency: _____ Project: _____ Date: _____

HORIZONTAL CONTROL - south zone

N 528,405.45 E 1,225,336.72 Datum/Adj.: 1927 Precision: 1/25,000
 Lat: 43°04'47" Long: 123°24'01" Agency: DCSO File # C.S.56/23 Date: 1973-1984
 N _____ E _____ Datum/Adj.: _____ Precision: _____
 Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____
 N _____ E _____ Datum/Adj.: _____ Precision: _____
 Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____
 N _____ E _____ Datum/Adj.: _____ Precision: _____
 Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____

DESCRIPTION AND TO REACH

DESC.: A STANDARD DCSO DISK STAMPED "WILLIS RM 1 1985" SET IN TOP OF 8 INCH O.D., CONCRETE FILLED, CONCRETE BELL TILE WHICH PROTRUDES APPROX. 4 INCHES ABOVE ROAD SHOULDER.

TO REACH: FROM THE INTERSECTION OF BROCKWAY RD. (CO. RD. # 47F) AND WILLIS CREEK RD. (CO. RD. # 43) IN T29S, R6W, SEC 32. PROCEED SE'LY ALONG WILLIS CREEK RD. APPROX. 2.1 MILES TO MONUMENT ON LEFT.

