

DOUGLAS COUNTY SURVEYOR'S OFFICE

R073020B

100-1181


100-1182

Designation: Z-019 Station: ZEBULON T ZIS R 11W S 20 ¼ SE

Date Set: 7-22-03 Set by (Agency): DCSO

Date Recovered: 7-22-03 Recovered by: RWS SJF

- Found New Reset
 Not Found Referenced Destroyed



VERTICAL CONTROL

NGVD 29 Elevation: 7.68 Feet File # CS 67/05
 Precision: 3rd Agency: DCSO Project: 2006 Date: 2003
 NAVD 88 Elevation: _____ Meters File # _____
 Precision: _____ Agency: _____ Project: _____ Date: _____


HORIZONTAL CONTROL - south zone

N _____ E _____ Datum/Adj.: 1927 Precision: 615
 Lat: 43° 43' 44.6" Long: 124° 01' 28.9" Agency: DCSO File # R073020B Date: 2003
 N _____ E _____ Datum/Adj.: _____ Precision: _____
 Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____
 N _____ E _____ Datum/Adj.: _____ Precision: _____
 Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____
 N _____ E _____ Datum/Adj.: _____ Precision: _____
 Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____

DESCRIPTION AND TO REACH

DCSO DRILL CAP STAMPED
'ZEBULON 2003' SET IN
NORTH WEST WING WALL OF
CONCRETE BRIDGE OVER
OTTER CREEK

FROM THE INTERSECTION OF
SOUTH SMITH RIVER RD. (CO. RD #195)
AND OTTER SLOUGH RD (CO. RD
#119) PROCEED SOUTH EASTERLY
ALONG OTTER SLOUGH ROAD
0.65 MILES TO CONCRETE
BRIDGE OVER OTTER CREEK





7.30.2003