


A simple line drawing of a person wearing a microscope, looking at a large 'Z' inside a semi-circle.

Date Recovered _____



VERTICAL CONTROL

Precision: _____ Agency: _____ Proj. # _____ Date: _____

Approximate Geographic Position: Latitude 43° 43' 06" Longitude 123° 13' 02"

SKETCH

A standard DCSO disk stamped "HONOR 1978" set in a concrete filled belltile 4 inches below ground.

From the intersection of Hwy.99 and I-5
access Rd. in T21S,R4W,Sec.30; proceed
northerly along Hwy. 99 0.5 miles to
to monument on left.

From the intersection of Hwy. 99 and
Co. Rd. #62 (Bear Crk. Rd.) in T21S,
R4W, Sec. 19; proceed southerly along
Hwy. 99 0.4 miles to monument on right.

A brass cap set in concrete filled belltile stamped "HONOR RM2 1978" bears N 19° 53' 47" E 33.96 ft. (grid)

Note: For further information, contact the Douglas County Surveyor's Office, Room 205 Douglas County Justice Building, Roseburg, OR 97470. Phone 440-4278. Douglas County residents outside the Roseburg calling area, dial toll free 1-800-452-0991.

