



B141

OFFICE OF THE
DOUGLAS COUNTY SURVEYOR

Station: BM 7-0.3
Date Set: ?
Set By (Agency): ?
Date Recovered: 8-18-94
Recovered By: RWS SJF

T 23 S, R 5W, Sec 3



- Found
- New
- Reset
- Not Found
- Referenced
- Destroyed

VERTICAL CONTROL

Elevation: 356.031 NGS Line # _____ USGS Line # _____ OSHD Line # _____
Precision: 3rd Agency: DCS Proj. # 2007 Date: 1994

HORIZONTAL CONTROL CORPSCON6 NAVD88 359.62 FT CS66/54

South Zone O.C.S. 27: Y(Northing) _____ X(Easting) _____

South Zone O.C.S. 83: Y(Northing) 714598 X(Easting) 4185942

Precision: GIS SCALED Agency: DLSO Proj. # _____ Date: 2014

Approx. Geographic Position: Latitude 43° 35' 38" Longitude 123° 16' 30"

DESCRIPTION and TO REACH

2 1/2" DIA BRASS CAP IN SOUTHWEST CORNER
OF CONCRETE ABUTMENT WING WALL, STAMPED
" 7-0.3 "

FROM THE INTERSECTION OF EAGLE VALLEY RD
(CO. RD # 389) FORMERLY STATE HWY 92) AND
ELK HEAD RD, (CO. RD # 7) IN T23S R5W SEC 3,
PROCEED EASTERLY ALONG ELK HEAD RD APPROX
0.3 MILES TO BRIDGE OVER SMALL CREEK AND
BOAT SPIKE IN SOUTHWEST CORNER,

Reference Marks:

