

PLSS 100500

OFFICE OF THE
DOUGLAS COUNTY SURVEYOR

Station: NORTHWEST CORNER T 25 S, R 5W, Sec 18

Set By (Agency): DCSO

Date Set: ~~1972~~ 1999

Recovered By LEM



Date Recovered 1981

Recovered By _____

Date Recovered _____

Recovered By _____

Date Recovered _____



250-05W-18-024 NW CORNER 25S 05W 18

NAD 645718.16 4164895.38
83 43°24'12" 123°20'49"

VERTICAL CONTROL

Elevation: _____ NGS Line # _____ USGS Line # _____ OSHD Line # _____

Precision: _____ Agency: _____ Proj. # _____ Date: _____

HORIZONTAL CONTROL

South Zone State Plane Coordinates: Y(Northing) _____ X(Easting) _____
NAD 27

Precision: 1/5000 Agency: DCSO Proj. # CALAPOOYA (2008) M13150 Date: 1981 1999

Approximate Geographic Position: Latitude 43°24'12" Longitude 123°20'44"

DESCRIPTION and TO REACH

SKETCH

Brass cap attached to galvanized iron pipe. See Douglas County Surveyor's Record of Government Corners Renewed.

See survey M131-50 for corrected corner location.

Reference Marks:

Note: For further information, contact the Douglas County Surveyor's Office, Room 205 Douglas County Justice Building, Roseburg, OR 97470. Phone 440-4278. Douglas County residents outside the Roseburg calling area, dial toll free 1-800-452-0991.