

OFFICE OF THE
DOUGLAS COUNTY SURVEYOR

Station: CYNTHIA T 27 S, R 5 W, Sec 19

Set By (Agency): DCSO

Date Set: 1982

Recovered By TP, IP


Date Recovered 7/82

Recovered By _____

Date Recovered _____

Recovered By _____

Date Recovered _____



c-124
CYNTHIA

27S 5W 19

NAD 572163.24 4165137.76
83 43°12' 5" 123°20'11"

VERTICAL CONTROL

Elevation: _____ NGS Line # _____ USGS Line # _____ OSHD Line # _____

Precision: _____ Agency: _____ Proj. # _____ Date: _____

HORIZONTAL CONTROL NAD 27

South Zone State Plane Coordinates: Y(Northing) 572,198.47 X(Easting) 1,244,179.42

Precision: 1/20,000 Agency: DCSO Proj. # 2005-2 Date: 1983

Approximate Geographic Position: Latitude 43°12'06" Longitude 123°20'07"

DESCRIPTION and TO REACH


SKETCH

DESCRIPTION:

A DCSO disk stamped "CYNTHIA 1982"
set flush in concrete curbing.

TO REACH:

From the intersection of SE Terrace Dr.
and SE Summit Dr. proceed westerly
along SE Terrace Dr. 0.12 miles to
monument on right.



Reference Marks:

Note: For further information, contact the Douglas County Surveyor's Office, Room 205
Douglas County Justice Building, Roseburg, OR 97470. Phone 440-4278. Douglas
County residents outside the Roseburg calling area, dial toll free 1-800-452-0991.