



OFFICE OF THE
DOUGLAS COUNTY SURVEYOR

Station: MELINDA
Date Set: 1991
Set By (Agency): DCSO
Date Recovered: 3/7/91
Recovered By: RWS,SJF
Date Recovered: _____
Recovered By: _____
Date Recovered: _____
Recovered By: _____

T 28 S, R 4 W , Sec 13



DESIG. M-094

VERTICAL CONTROL

Elevation: 1112.424 NGS Line # _____ USGS Line # _____ OSHD Line # _____
Precision: 2nd Agency: DCSO Proj. # 2007 Date: 1991

HORIZONTAL CONTROL CORPSCON6 NAVD88 1115.98 FT, CS 66/43

South Zone O.C.S. 27: Y(Northing) _____ X(Easting) _____

South Zone O.C.S. 83: Y(Northing) 544197 X(Easting) 4221552

Precision: GIS SCALED Agency: DCSO Proj. # _____ Date: 2014


Approx. NAD ⁸³ Geographic Position: Latitude 43°07'48" Longitude 123°07'13"

DESCRIPTION and TO REACH

SKETCH

A DCSO disk stamped "MELINDA 1991" set in the southeast corner of bridge abutment crossing North Myrtle Creek.

From the intersection of North Myrtle Rd. (Co.Rd.#15) and Slide Creek Rd. (Co.Rd.#149) in T28S,R4W,Sec.33, proceed 4.25 miles northeasterly along North Myrtle Rd. to monument on the right.



Reference Marks:

Note: For further information, contact the Douglas County Surveyor's Office, Room 205 Douglas County Justice Building, Roseburg, OR 97470. Phone 440-4278. Douglas County residents outside the Roseburg calling area, dial toll free 1-800-452-0991.