

OFFICE OF THE
DOUGLAS COUNTY SURVEYOR

Station: Robin RM 1

T 28 S, R 4W , Sec 34

Date Set: 1992

Set By (Agency): DCSO

Date Recovered: 1992


Recovered By: TE- STE

Date Recovered: _____


Recovered By: _____

Date Recovered: _____

Recovered By: _____



NAD 83 529360.64 4208877.91
83 43° 5'17" 123°10' 3"



VERTICAL CONTROL NGVD 29

Elevation: 871.8 NGS Line # _____ USGS Line # _____ OSHD Line # _____

Precision: GPS Agency: DCSO Proj. # 2008 Date: 1992

HORIZONTAL CONTROL OCS 27

South Zone O.C.S. 27: Y(Northing) 529,396.33 X(Easting) 1,287,919.46

South Zone O.C.S. 83: Y(Northing) _____ X(Easting) _____

Precision: 1/25,000 Agency: DCSO Proj. # 2008 Date: 1992

Approx. NAD 83 Geographic Position: Latitude _____ Longitude _____


DESCRIPTION and TO REACH

SKETCH

Set: A standard DCSO disk stamped "Robin RM 1 1992"
set in the NW corner of bridge deck.

To Reach: At the intersection of North Myrtle Rd. (Co.
Rd. #15; and Slide Creek Rd. (Co. Rd. #148) in
T28S, R4W, sec. 34. Mon. is approx. 300 ft. East
on Slide Creek at bridge crossing North Myrtle Creek.

Reference Marks:



Note: For further information, contact the Douglas County Surveyor's Office, Room 205
Douglas County Justice Building, Roseburg, OR 97470. Phone 440-4278. Douglas
County residents outside the Roseburg calling area, dial toll free 1-800-452-0991.