

OFFICE OF THE  
DOUGLAS COUNTY SURVEYOR

Station: M78

T 29 S, R 5W , Sec 22

Date Set: 1991

Set By (Agency): City of M.C.

Date Recovered: 10/7/91



Recovered By: Ruppert LS 866

Date Recovered: \_\_\_\_\_

Recovered By: \_\_\_\_\_

Date Recovered: \_\_\_\_\_

Recovered By: \_\_\_\_\_



M-078                      295 5W 22  
M78

NAD            510496.30            4177804.14  
83            43° 2' 1"            123°16'53"

VERTICAL CONTROL    NGVD 29

Elevation: 749.6                      NGS Line # \_\_\_\_\_                      USGS Line # \_\_\_\_\_                      OSHD Line # \_\_\_\_\_

Precision: GPS                      Agency: DCSO                      Proj. # 2017-1 CS 64/22                      Date: 1991

HORIZONTAL CONTROL

South Zone O.C.S. 27: Y(Northing) 510,531.88                      X(Easting) 1,256,845.68

South Zone O.C.S. 83: Y(Northing) \_\_\_\_\_                      X(Easting) \_\_\_\_\_

Precision: 1/15,000                      Agency: DCSO                      Proj. # 2017-1 CS 64/22                      Date: 1991


Approx. NAD 83 Geographic Position: Latitude \_\_\_\_\_                      Longitude \_\_\_\_\_

DESCRIPTION and TO REACH

SKETCH

Set: A standard DCSO disk stamped "M78 1991"  
set in a mass of concrete.

To Reach: Mon. is set on the east side of Spruce St.  
in the bottom of ditch in line with the  
South side of Laurance St. in Myrtle  
Creek.



Reference Marks:

Note: For further information, contact the Douglas County Surveyor's Office, Room 205  
Douglas County Justice Building, Roseburg, OR 97470. Phone 440-4278. Douglas  
County residents outside the Roseburg calling area, dial toll free 1-800-452-0991.