



OFFICE OF THE
DOUGLAS COUNTY SURVEYOR



Station: LAKE
Set By (Agency): O.S.H.D.
Date Set: UNKNOWN
Recovered By FLI (DCSO)
Date Recovered 7/23/84
Recovered By _____
Date Recovered _____
Recovered By _____
Date Recovered _____

UNS
T 26 S, R 5E , Sec 36



VERTICAL CONTROL NGVD 29

Elevation: 4504.926 NGS Line # _____ USGS Line # _____ OSHD Line # _____
Precision: 2nd Agency: DCSO Proj. # 2008-1 CS62/23 Date: July 1984

HORIZONTAL CONTROL


South Zone State Plane Coordinates: Y(Northing) _____ X(Easting) _____
Precision: _____ Agency: _____ Proj. # _____ Date: _____
Approximate Geographic Position: Latitude _____ Longitude _____

DESCRIPTION and TO REACH

Along Highway 138, 0.1 mile
east of Lake Creek, and 0.3 mile
east of Lemolo Lake Junction.

Unstamped brass cap in con-
crete post, 35 ft. south of Highway
138, 38 ft. east of edge of old
gravel road.

SKETCH



Reference Marks:

Note: For further information, contact the Douglas County Surveyor's Office, Room 205
Douglas County Justice Building, Roseburg, OR 97470. Phone 440-4278. Douglas
County residents outside the Roseburg calling area, dial toll free 1-800-452-0991.