

OFFICE OF THE
DOUGLAS COUNTY SURVEYOR

Station: RAYNOR

T 26 S, R 6W, Sec 18


Date Set: 1998

R-106


Set By (Agency): DCSO

Date Recovered: 11-3-98

Recovered By: KWS SIF



- Found
- New
- Reset
- Not Found
- Referenced
- Destroyed



VERTICAL CONTROL NGVD 29

Elevation: 386.80 NGS Line # _____ USGS Line # _____ OSHD Line # _____

Precision: 3rd Agency: DCSO Proj. # 2007 Date: 1998

CS File # 661020

HORIZONTAL CONTROL

South Zone O.C.S. 27: Y(Northing) _____ X(Easting) _____

South Zone O.C.S. 83: Y(Northing) _____ X(Easting) _____

Precision: _____ Agency: _____ Proj. # _____ Date: _____

Approx. NAD 83 Geographic Position: Latitude _____ Longitude _____

DESCRIPTION and TO REACH

DCSO BRASS CAP SET TOP OF LARGE ROCK MARKED
"RAYNOR 1998"

FROM THE INTERSECTION OF GARDEN VALLEY RD
(CO RD #6) AND LOWER GARDEN VALLEY RD
(CO RD #191) IN T26S R6W SEC 19, PROCEED
NORTHEAST ALONG GARDEN VALLEY RD 0.35 MILES
TO MONUMENT ON LEFT.

Reference Marks:

