


G15 R 021200C DOUGLAS COUNTY SURVEYOR'S OFFICE

Designation: S-198 Station: SING-3 T 26 R 6W S 32 1/4 SE

Date Set: 2003 Set by (Agency): DCSO

Date Recovered: 2-10-03 Recovered by: RWS SIF

☒ Found ☐ New ☐ Reset
☐ Not Found ☐ Referenced ☐ Destroyed



VERTICAL CONTROL

NGVD 29 Elevation: 393.23 Feet File # CS66/62
 Precision: 3rd Agency: DCSO Project: 2007 Date: 2003
 NAVD 88 Elevation: _____ Meters File # _____
 Precision: _____ Agency: _____ Project: _____ Date: _____

HORIZONTAL CONTROL - south zone

N _____ E _____ Datum/Adj.: 1929 Precision: G15
 Lat: 43°15'54.5" Long: 123°25'50.4" Agency: DCSO File # CS66/62 Date: 2003
 N _____ E _____ Datum/Adj.: _____ Precision: _____
 Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____
 N _____ E _____ Datum/Adj.: _____ Precision: _____
 Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____
 N _____ E _____ Datum/Adj.: _____ Precision: _____
 Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____

DESCRIPTION AND TO REACH

DCSO DRILL CAP STAMPED
"SING-3 2003" SET IN
TOP OF 36" DIA CONCRETE
DRAIN CULVERT
FROM THE INTERSECTION
OF QUAIL LN (CO. RD #138)
AND GARDEN VALLEY RD
(CO. RD #6) IN T26S R6W
SECTION 32 PROCEED
WESTWARD ALONG QUAIL LN
1.15 MILE TO MONUMENT
ON LEFT

