


OFFICE OF THE
DOUGLAS COUNTY SURVEYOR



Station: CHARTER T 22 S, R 64, Sec 15


Date Set: 2000

Set By (Agency): DCSO

Date Recovered: 3-30-2000

Recovered By: RUS SLF

- Found
- New
- Reset
- Not Found
- Referenced
- Destroyed



C-170

VERTICAL CONTROL NGVD 29 CORPSCONG NAVD 469.34 FT

Elevation: 465.87 NGS Line # _____ USGS Line # _____ OSHD Line # _____

Precision: 3rd Agency: DCSO Proj. # 66/38 Date: 2000

HORIZONTAL CONTROL

South Zone O.C.S. 27: Y(Northing) _____ X(Easting) _____

South Zone O.C.S. 83: Y(Northing) _____ X(Easting) _____

Precision: _____ Agency: _____ Proj. # _____ Date: _____

Approx. NAD 83 Geographic Position: Latitude 43° 13' 15.7" Longitude 123° 23' 41.8"

27 43° 13' 16.3" 123° 23' 37.5"

DESCRIPTION and TO REACH

DCSO DRILL CAP STAMPED "CHARTER 2000"
SET IN CONCRETE PAD OF BUS STOP COVER

GO TO THE INTERSECTION OF CHARTER OAKS AND
TRUST ST MONUMENT IS AT EAST CORNER
OF CONCRETE PAD SOUTH WEST OF INTERSECTION.

Reference Marks:

