

OFFICE OF THE
DOUGLAS COUNTY SURVEYOR

Station: M72

T 29 S, R 5W , Sec 27

Date Set: 1991

Set By (Agency): City of M.C.

Date Recovered: 10/16/91


Recovered By: Ruppert LS 866

Date Recovered: _____

Recovered By: _____

Date Recovered: _____

Recovered By: _____



M-072
M72 29S 5W 27

NAD 506387.32 4180962.78
83 43° 1'21" 123°16' 9"

VERTICAL CONTROL

Elevation: 700.0 NGS Line # _____ USGS Line # _____ OSHD Line # _____

Precision: GPS Agency: DCSO Proj. # 2017-1 CS64/22 Date: 1991

HORIZONTAL CONTROL

South Zone O.C.S. 27: Y(Northing) 506,422.92 X(Easting) 1,260,004.33

South Zone O.C.S. 83: Y(Northing) _____ X(Easting) _____

Precision: 1/15,000 Agency: DCSO Proj. # 2017-1 CS64/22 Date: 1991


Approx. NAD 83 Geographic Position: Latitude _____ Longitude _____

DESCRIPTION and TO REACH

SKETCH

Set: A standard DCSO disk stamped "M72 1991"
set in a mass of concrete flush with
ground.

To Reach: At the interseciton of Riverside Dr. (Co. Rd. 18A)
and Cerrito Ct. in Myrtle Creek.



Reference Marks:

Note: For further information, contact the Douglas County Surveyor's Office, Room 205
Douglas County Justice Building, Roseburg, OR 97470. Phone 440-4278. Douglas
County residents outside the Roseburg calling area, dial toll free 1-800-452-0991.