


DOUGLAS COUNTY SURVEYOR'S OFFICE

Designation: 90-164 Station: 16+32.78 T 27S R 6W S 14 1/4 NE

Date Set: 1990 Set by (Agency): AA SURVEYING

Date Recovered: 9/08 Recovered by: SJF

- Found New Reset
 Not Found Referenced Destroyed



VERTICAL CONTROL

NGVD 29 Elevation: 432.41 Feet File # M 112-20A4B
 Precision: 3RD. ORDER Agency: L.S. 1651 Project: M 112-20A8B Date: 1990
 NAVD 88 Elevation: _____ Meters File # _____
 Precision: _____ Agency: _____ Project: _____ Date: _____

HORIZONTAL CONTROL - south zone

N 580529.86 E 4154733.36 Datum/Adj.: NAD 83 Precision: SCALED
 Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____
 N _____ E _____ Datum/Adj.: _____ Precision: _____
 Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____
 N _____ E _____ Datum/Adj.: _____ Precision: _____
 Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____
 N _____ E _____ Datum/Adj.: _____ Precision: _____
 Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____

DESCRIPTION AND TO REACH

A 2 5/8 INCH DIAM. BRASS CAP
STAMPED "AA SURVEYING INC", ON
A 1 1/2 x 36 INCH GALV. IRON PIPE,
SET BELOW ASPHALT ROAD SUR-
FACE, UNDER A 7 INCH DIAM.
ALUMINUM MONUMENT COLLAR
AND COVER.

GO TO THE INTERSECTION OF
PRIMROSE LANE AND NW KEASEY
ST. IN THE NE QUARTER OF
SECTION 14, T27S, R6W. MON-
UMENT FALLS JUST NORTH
OF THE ABOVE INTERSECTION
NEAR THE ♀ OF NW KEASEY ST.




PHOTO FILE NAME

LOCATION

100-1341 (Renamed 90-164
7/28/09)

~~M092511A~~ BAD FILE

PROCESSED BY: _____

DATE: _____