


**DOUGLAS COUNTY SURVEYOR'S OFFICE**

Designation: 70-167 Station: 32+17.80 T 27S R 6W S 14  $\frac{1}{4}$  NE

Date Set: 1990 Set by (Agency): A.A. SURVEYING

Date Recovered: 9/08 Recovered by: SJF

- Found                       New                       Reset
- Not Found                   Referenced             Destroyed



VERTICAL CONTROL

NGVD 29 Elevation: 440.33 Feet      File # M112-20 A+B  
 Precision: 3RD. ORDER      Agency: L.S. 1651      Project: M112-20A+B      Date: 1990  
 NAVD 88 Elevation: \_\_\_\_\_ Meters      File # \_\_\_\_\_  
 Precision: \_\_\_\_\_      Agency: \_\_\_\_\_      Project: \_\_\_\_\_      Date: \_\_\_\_\_

HORIZONTAL CONTROL - south zone

N 582115.77      E 4154758.62      Datum/Adj.: NAD83      Precision: SCALED  
 Lat: \_\_\_\_\_      Long: \_\_\_\_\_      Agency: \_\_\_\_\_      File # \_\_\_\_\_      Date: \_\_\_\_\_  
 N \_\_\_\_\_      E \_\_\_\_\_      Datum/Adj.: \_\_\_\_\_      Precision: \_\_\_\_\_  
 Lat: \_\_\_\_\_      Long: \_\_\_\_\_      Agency: \_\_\_\_\_      File # \_\_\_\_\_      Date: \_\_\_\_\_  
 N \_\_\_\_\_      E \_\_\_\_\_      Datum/Adj.: \_\_\_\_\_      Precision: \_\_\_\_\_  
 Lat: \_\_\_\_\_      Long: \_\_\_\_\_      Agency: \_\_\_\_\_      File # \_\_\_\_\_      Date: \_\_\_\_\_  
 N \_\_\_\_\_      E \_\_\_\_\_      Datum/Adj.: \_\_\_\_\_      Precision: \_\_\_\_\_  
 Lat: \_\_\_\_\_      Long: \_\_\_\_\_      Agency: \_\_\_\_\_      File # \_\_\_\_\_      Date: \_\_\_\_\_

DESCRIPTION AND TO REACH

A 2 5/8 INCH DIAM. BRASS CAP  
STAMPED "AA SURVEYING INC." ON  
A 1 1/2 x 36 INCH GALV. IRON PIPE,  
SET BELOW ASPHALT ROAD  
SURFACE UNDER AN 11 1/2 INCH DIAM  
CAST-IRON MONUMENT COLLAR  
AND COVER.

GO TO THE INTERSECTION OF  
N.W. KEASEY ST. AND CALKINS  
AVE. IN THE N.E. QUARTER OF  
SECTION 14, T27S, R6W. MONU-  
MENT FALLS JUST NORTH OF THE  
ABOVE INTERSECTION NEAR THE  
☐ OF N.W. KEASEY ST.

