

Survey No.

Made for

L Hatfield

T. 28 S. R. 4 W

To establish corners and boundaries of Lots 1 and 2 of Section 6, T. 28 S. R. 4 W.

Begin at N. E. cor. of Section 6 which I reestablish from the original witness tree in Sec. 5, set a post 4x4x36, marked C5 55 56 28 5 4 W. Other witness trees have been destroyed. At 10:30 a.m. l.m. to I set off 23°25' on decl. arc and 43°10' on lat. arc and determine a meridian at this corner. Thence I run

West

39.93

On North line of Sec 6. Variation 20°30' East Intersect W. line of Lot #2, 33 links S. of 1/4 Sec cor in North Bdy of Sec. 6 which I reestablish from the original B. T. in Sec 31 T. 27 S. R. 4 W. As this tree is small and marks are damaged in cutting tree open I reestablish this 1/4 Sec corner as follows - set a W. Oak post, 4x4x36, marked 1/4 5 56 28 5 4 W, from which a W. Oak, 6" diam, marked C5 1/4 5 56 BT bears S. 28° W. 68 links and a Red Fir 14" diam, marked C5 1/4 5 56 BT, bears N. 72° E. 38 links: Thence I run

N. 89° 32' E

19.96 1/2

On true N. line of Sec 6 1/16 Sec cor, set a post, 4x4x36, marked C. 5 1/16 5 56 5 31 from which a Cedar, 12" diam, marked C5 1/16 5 BT. bears S. 57 1/2° E. 35 links and a Red Fir, 8" diam. marked C. 5 1/16 5 BT, bears S. 68 3/4° W. 19 links. To cor to Sec 5 - 6 - 31 - 32

39.93

June 18th, 1913.

South

41.63

Begin at post established for cor of Sections 5-6-31 & 32 On Random bet. Secs. 5 and 6 1/4 Sec post which I establish from the original witness tree bears East 102 links.

N. 1° 24' W.

20.00

On true line between Sections 5 and 6 1/16 Sec cor, set a post 4x4x36 marked C5 1/16 5, from which a Red Fir, 9" diam, marked C5 1/16 5 BT bears N. 68 1/2° W 60 links and a Red Fir, 10" diam marked C5 1/16 5 BT. bears S 6° W 50 links.

41.63

To Sec. Cor.

June 19th, 1913.