

Survey No.

Made for

40.17 Intersect North and South center line of Sec 6
32 links North of 1/6 Sec. corner.

N 89° 18' W. On true East and West center line of S. W. 4 of Sec 6.
20.01 1/6 Sec cor. (Center post of S. W. 4 of Sec 6) set a post
4x4x36 marked 1/6 SCS from which a Red
Fir 16" diam, marked C 5 1/6 SBT bears S 33 1/2° E
52 links and a Red Fir, 14" diam marked C 5 1/6 S
BT. bears N. 59° W 59 links.

40.17 To 1/6 Sec corner.

June 24th 1913.

Begin at post established for 1/4 Sec cor in West
boundary of Sec 6

North On West boundary of Sec 6
19.97 1/2 Set post temporary 1/6 Sec cor.
39.95 To North West corner of Sec 6.

South On West boundary of Sec 6
19.97 1/2 1/6 Sec cor set post 4x4x36, marked C 5 1/6 S
from which a White Oak 26" diam, marked
C 5 1/6 SBT bears N. 74 1/2° W. 61 links and a
Black Oak 18" diam marked C 5 1/6 SBT bears
S 42 1/2° E. 24 links.

June 25th 1913.

Begin at post established for 1/4 Sec cor in North
boundary of Sec 6.

West On North line of Sec 6
5.00 Top of Ridge c N. E. - N. W. cor of Sec 6 visible
in line.

20.00 1/6 Sec cor set a post 4x4x36, marked C 5 1/6 S from which a
a Red Fir, 10" diam, marked C 5 1/6 SBT bears S 57° W. 45 lks and a
Red Fir, 26" diam, marked C 5 1/6 SBT, bears S 17° E. 85 links. June 26th 1913

Recorded June 26th 1913.

C. J. Boyer
Deputy Co. Surveyor