

County Surveyor's Record, Douglas County, Oregon

Survey No. ....

Made for. ....

by setting a cedar post 4"x4"x3 1/2' marked as per instructions and from which

Original B.T.'s a fir 20" in dia bears N 70° 20' E 80 lbs  
 " " 20 " " " " " " N 82° 15' E 55 "  
 " " 42 " " " " " " S 72° 30' E 125 "  
 " " 24 " " " " " " S 17° 25' N 138 "  
 Oak 5" " " " " " " N 59° N. -

Thence I run.

S 89° 56' N  
38.10

On a random line bet Sec 5 and 32 Van 21° 18' E.  
 Intersect 9 lbs South of 1/4 post. which I establish as per original B.T.'s trees, destroyed but stumps standing badly decayed. I renew corner by setting a charred cedar post 4"x4"x3 1/2' from which

A Red Fir 10" marked C.S. 1/4 S to. S 39° 05' E 56 lbs  
 " " " 5" " " " " " S 28° N 60 "

S 89° 56' E  
38.10

On true line  
 To Sec Corner.

S 89° 56' N  
39.03

From the 1/4 post bet 5+32,  
 On random line

Intersect 35 lbs South of Cor Sec 5, 6 31, & 32.  
 which I renew per original B.T.'s trees destroyed but stumps standing Set an Oak post 4 x 4 x 3 1/2 marked as per instructions from which

A fir 12" in dia, <sup>mkd.</sup> C.S. 31 J 28 S R 4 N B.T. to N 37 1/2° N 106 lbs  
 " " 12 " " " " 32 " " " " " " " N 34 1/2° E 92 "  
 Pine 42" " " " 5 " 29 " " " " " " S 29 1/2° E 210 "  
 Fir 22 " " " 5 " " " " " " " S 21° E 160 "

S 89° 34' E  
39.03

On true line  
 To 1/4 Corner.

S 0° 16' E  
38.28.

From the corner to sections 5-6-31-32 I run  
 On a random bet Sec 5 + 6.

N 1° 06' E  
38.28

Intersect 95 lbs East of 1/4 post.  
 On true line bet Sec 5+6.  
 To Sec Corner.