

County Surveyor's Record, Douglas County, Oregon

Survey No.

Made for *W. T. Thomas for S. Marks & Co.*

T. 28 S. R. 5 W.
Sec. 9.
July 9, 1915

~~Section 8 & 9~~
Page 61 61

To identify a tract of land described as follows, the S.E. 1/4 of the N.W. 1/4 of Sec. 9 T. 28 S. R. 5 W.

I set up the traverse at the S.W. corner of the 40 acre tract under wire fence and said by Jim Adams to be the tract in dispute.

I find a wire fence leading approximately west to four or five minutes, which I determine by Solar bearing. I took the fence as direction and chain nearly due west intersect Sec. line at 1/4 corner between sec 8 & 9, which I locate from Original bearing trees.

20.22

Then I ran South compass line to locate the corner to Secs 8, 9, 16 & 17, for further identification.

40.50

Intersect Sec line 49 ^{W.P.} west of anchor post at corner of fence. I check the place where the post is located and find the Oak tree gone but the rotten bottom of stump surrounded by second growth.

Third Ash N. 67° E. still in place Indications of old blazes plain but Original marker rotted out.

Ash S. 52° E. find rotten stump surrounded with second growth, from measurements the fence post referred to is in correct position.

F. J. Cole Deputy Surveyor.