

County Surveyor's Record; Douglas County, Oregon

Survey No.

Made for. H. K. Lawrence

Sec 5 Tp 29 S R 4 W

May 15 1915

F. J. Cole and J. J. Black chainmen with Burdick marker
Beginning at the cor of Secs. 4, 5, 8, & 9 Tp. 29 S R 4 W.

Take observation on Sun in latitude calculated N. $+3^{\circ}05'$

Sun Dec' May 15th 9:00 A.M. N. $15^{\circ}43'36''$ + 3 hrs. eq. $36'' = 18^{\circ}44'12''$
- var - $20^{\circ}00'E$

This corner I know by original B.T.s. two of which I find standing. I remark new trees as follows:

- a. Fir 24" in dia. bears. N. $15^{\circ}10'E$ 25 lks.
- a. W. " 10" " " " N. $80^{\circ}25'W$ 70 "
- " " " 12" " " " S. $14^{\circ}20'E$ 27 "

Thence I run

W. lat.
40.48

on random between Secs. 5 and 8

intersect 3 lks. North of $\frac{1}{4}$ post, which I establish by original B.T. the stump of which is standing, to run an Ash 20" bro. S. $85^{\circ}E$ 40 lks. I renew $\frac{1}{4}$ post by setting new post $4 \times 4 \times 3\frac{1}{2}$ marked C.S. from which:

- An Alder 26" in dia. bears. N. $88^{\circ}11'E$ 272 lks
- " " 6" " " " S. $78^{\circ}09'E$ 35 "

From $\frac{1}{4}$ post between 5 & 8 continue:

W. lat.
40.03

intersect 32 lks. North of cor. Secs. 5, 6, 7, & 8. original B.T.s. destroyed by fire, but stumps remaining. This corner I renew by setting an Oak post $4 \times 4 \times 3\frac{1}{2}$ properly marked. I renew B.T.s. as follows:

- a. Fir 34" in dia. bears. S. $34^{\circ}45'W$ 151 lks.
- " " 42" " " " N. $37^{\circ}W$ 151 "
- " " 18" " " " N. $39^{\circ}15'E$ 36 "
- " " 16" " " " S. $73^{\circ}E$ 39 "

- var. $20^{\circ}30'E$ -

Thence from cor of Secs. 5, 6, 7, & 8

N. $89^{\circ}32'E$
20.01 $\frac{1}{2}$

on true line south boundary Sec 5

at intersection cor. post $4 \times 4 \times 3\frac{1}{2}$ marked $\frac{1}{16}$ S. from which:

- a. Fir 36" marked $\frac{1}{16}$ S. bears. N. $68^{\circ}W$ 15 lks.
- " " 48" " " " S. $37^{\circ}E$ 69 "

40.03

to $\frac{1}{4}$ Sec post

For Complete Record see pages 222-226