

County Surveyor's Record, Douglas County, Oregon

Survey No. 29 SRW

Made for H. H. Lawrence

Beginning at the Cor of Secs. 4, 5, 32 + 33 Establish cor from original B.T.E. do not agree in bearing - due to old measurements being taken on slope. I use B.T.s. in Sec 5 + 33. Renew corner by setting cedar post 4" x 3 1/2" properly marked, and renew & re-mark following for new B.T.s. to wit:

Old B.T. 20" in dia.	Bears. N. 70° 20' E	80 lks
" " 20" "	" " N 82° 15' E	55 "
" " 42 "	" " S. 72° 30' E	125 "
" " 24 "	" " S. 17° 25' W	138 "
Oak 5 "	" " N. 59° W	

Thence on random bet Secs 5 + 32 - var. 21° 18' E -

Intersect 9 lks South of 1/4 Sec post, which I renew per original B.T.s. badly decayed but stumps remaining. Set charred cedar post 4" x 3 1/2" marked S 1/4 S. from which:

a Fir 10" in dia	bears. S. 39° 05' E.	56 lks
" " 5" "	" " S 28° W	60 "

From above 1/4 post I continue on random bet Secs 5 + 32

Intersect 35 links South of Cor. Secs. 5, 6, 32 + 31 which I renew by original B.T.s. badly decayed stumps standing. Set an Oak post 4" x 4" x 3 1/2" properly marked, from which:

a Fir 12" in dia.	bears. N 37° 30' W	106 lks,
" " 12" "	" " N 34° 30' E.	92 "
" Pine 42" "	" " S 29° 30' E.	210 "
" Fir 22" "	" " S 21° E	160 "

From the above corner I run on random bet Secs. 5 and 6, - cloudy - var 18° 21' - assumed -

Intersect 95 links East of 1/4 post, original B.T.s. standing I renew 1/4 post by fir post 5" x 5" x 3 1/2" marked S 1/4 S from which:

A. Fir 40" in dia	bears. S. 77° E	78 lks,
" " " " "	" " N. 64° 45'	68 "

Thence I run on a random line through center Sec 5

Intersect 118 lks North of 1/4 post bet Sec + 35

S 89° 56' W
11.24
38.10

W 1/4
77.13

South
38.78

East
78.73