

County Surveyor's Record, Douglas County, Oregon

Survey No.

Made for

J. C. Gibson

F 23 S R 5 W

Feb 9 1916.

J. W. Cole
deputy Co. S.

F. B. 19 = 64

Page 26

Survey made to determine the SW. Corn. of
Gibbons land, being 120 Acres in the NW Cor. of
the N^m Wilson D. L. C. 45.

Chain - - W. W. Wilson and J. W. Cole

Cloudy No Sun for observations

Present E. O. Jockel, J. C. Gibson, Joe Gibson
Joe Wilson, and John Hise.

Begin at the approximate NW Cor. to Cl. 45
find ^{Oak} stump of original Witness Tree with marks
visible on inside of shell. Set at tree and run
S 10° E 29 li according to field notes Set temp. stakes
no evidence of Rock
measure S 82° W 29 li and search for remains of
Oak Bd. Find remains of oak S 88° W 29 li but
location of tree is very indefinite on account of
being badly decayed. Set a concrete block 5x8x12
for corner in place of temp stake and from which

A Tin 18" in dia br. S 20° W 46 li

" " 18 " " " S 48 1/2° E 59 li

On Random True 21° 30' E.

Set Temp SW Cor. of Gibbons land.

Intersect 117 li W of S.E. Cor. Cl. 45 dist not
measured after passing 20.00 Ch point

True line S 0° 51' E.

Return to stakes at 20.00 Chs Set East 30 lks

Set Oak stakes 3" x 3" x 3/2 for SW Corner of Gibbons
prop. from which A Tin 10 dia br. S 56° W 112 li

Oak Oak "10 " " 77 57 55 4 30 8 90"

True Mkd C.S. Bd. Stake mkd C.S.

Old True Corner S 10 lks and E 15 lks

Course of fence Easterly.

Corner as Set and Witness was accepted as SW Cor
of Gibbons Property by all parties concerned.

→ See Field Book 19 page 27 for Signatures

South

20.00

79.50