

COUNTY SURVEYOR'S RECORD, DOUGLAS COUNTY, OREGON

BUSHORS & CO. PORTLAND, ORE. 87545

Light House Survey SHEET 2

Survey No. 10 Made on
 In Town. Range Sec.
 Made for U.S. Dept of Lighthouses 17th Dist
 Portland, Ore
 Purpose of to establish boundaries of
 Umpqua River Light House Reserve

Survey No. Made on
 In Town. Range Sec.
 Made for
 Purpose of

SHEET 2

(Continued from sheet one)

and find the bearing to be N.48°-25'E. 10.02 chains along the Pacific Ocean.

Thence I returned to the quarter corner between sections 13 and 14 and picking up my bearing from the west line of section 13, which bears due North I ran a line East, through section 13 and tie in to the original quarter corner between sections 13 T.22 S., R.13 W. and 18, T.22 S., R.12 W., which I identified from the old original government witness trees, this line east and west through the center of the section, I find to bear S.88°-20'E; 79.59 chains between the quarter corner on the east and the quarter corner on the west of section 13 and I find the half section line between the quarter corner on the north and the quarter corner on the south of section 13 to be S.0°-26'E. 77.95 chains. then I set the true corner for the center of section 13, from which a 30" fir bears N.50°E. 25 ft. marked C.S. C.S. B.T. a 30" leaning spruce bears N.20°W. 42 ft. marked C.S. C.S. B.T. a 12" fir bears S.45°W. 16 ft. marked C.S. C.S. B.T. and a 36" spruce bears S.13°E. 30 ft. marked C.S. C.S. B.T.

Then I set the North center sixteenth corner on the N.E. corner of the Light House Reserve at N.0°-26'W., 38.97 chains from the center of the section from which a 30" spruce bears west $3\frac{1}{2}$ links, marked C.S. 1/16 B.T.

Thence from the true center of section 13, I ran S.0°-26'E. and at 10.74 chains set a witness corner on the North bank of Lake Marie, from which an 8" spruce bears S.30°W. 15 ft., marked C.S. W.C. B.T., the S.E. corner of the Light House Reserve falling in the lake, (the S1/16th cor. on the $\frac{1}{2}$ sec. line) I set a witness corner on the west bank of Lake Marie 50.5 links N.89°-02'W. of the true sixteenth corner from which witness corner a 14" hemlock bears S.85°E. 15 ft., marked C.S. W.C. B.T.

Thence I ran N.89°-02'W. and at 26.18 chains from the sixteenth corner in Lake Marie I set a witness corner or point in the edge of the vegetation from which a 12" pine bears S.35°E. 4.5 ft., marked C.S. W.C. B.T. thence on the same bearing I ran 13.76 chains to the S... corner of the Light House Reserve.

Thence I returned to the N.E. corner of the S.E. $\frac{1}{4}$ of the N.W. $\frac{1}{4}$ of section 13 and ran N.87°-32'W. 19.97 chains where I set an interior "L" corner of the Light House Reserve from which a bull pine bears S.5°E. 13 ft. marked C.S. N.W. 1/16 S. 13 B.T., thence I continued this line on, 19.71 chains to the N. 1/16th corner of section 13.

Thence I went to the N.E. corner of the N.W. $\frac{1}{4}$ of the N.W. $\frac{1}{4}$ of section 13 and ran S.0°-36'E. 18.5 chains to the S.E. corner of the N.W. $\frac{1}{4}$ of the N.W. $\frac{1}{4}$ of section 13 as previously noted and as marked by a 10" bull pine witness tree.

Signed,

H. L. Epstein
 County Surveyor,
 Douglas County, Oregon.