

COUNTY SURVEYOR'S RECORD, DOUGLAS COUNTY, OREGON

BEHRENS & CO. PORTLAND, ORE. 87545

<p>Survey No. Made on Nov. 1946</p> <p>In Town. 29 S Range 5 W Sec. 5</p> <p>Made for Frank Ritzow</p> <p>Purpose of</p> <p>C.S. FILE No. 40/58</p>	<p>Survey No. Made on May 1947</p> <p>In Town. 29 S Range 5 W Sec. 33</p> <p>Made for J. P. Brill</p> <p>Purpose of To subdivide the Brill property</p> <p>C.S. FILE No. 40-57</p>
--	--

FROM RESEARCH MADE 9/23/46 THIS APPEARS TO BE IN T 29 - 4 S. 5 V.R.

The original plat got away to the client but the work sheet is enclosed with the legal description of it.

Survey was started at the South $\frac{1}{4}$ corner and run through to the North $\frac{1}{4}$ corner and thence traversed according to the description.

An error in the original survey of bearing accounts for the whole being platted and it was finally passed for title insurance.

R.R. Ecker

John Adams D.L.C. No 41, T 29 S, R 5 W, W.M.
For J.P. Brill and Earl Carle, Myrtle Creek, Oregon.

This survey performed to subdivide the Brill property into three parcels one of which is further subdivided by Mr. Carle as shown on the map attached hereto.

The large work sheet attached shows that the survey was controlled by another survey done by us for Mr. McCoy and which property dove tails into the Brill piece.

There is a good deal of controversy about the $\frac{1}{4}$ corner on the East of Section 33 and I find a iron pipe and no other evidence as indicated on the tracing attached and after reconnaissance where the $\frac{1}{4}$ corner should be, I find nothing.

Costs will not permit the reestablishment of the $\frac{1}{4}$ corner so I make a new tie, the Southwest corner of the Lazuras right D.L.C. No 45, T 29 S, R 5 W, W.M.

R.R. Ecker, L.S. 158