

AN A.L.T.A. SURVEY FOR REUBEN AND PROCTOR  
 IN N ½ OF SECTION 11, T28S, R6W, W.M.

**CERTIFICATION**  
 I HEREBY CERTIFY THAT THIS SURVEY, MADE UNDER MY SUPERVISION ON 10-4-65, CORRECTLY SHOWS THE LOCATION OF THE BUILDINGS AND OTHER STRUCTURES TO THE NEARLY CENTER OF THE LAND ADJACENT HERETO AND THAT THERE ARE NO ENCUMBRANCES OF ADJOINING BUILDINGS OR STRUCTURES OTHER THAN SAID LAND, NOR OVERLAP OF BUILDINGS OR STRUCTURES AS THEY SAID LAND EXCEPT AS SHOWN.

DAVID R. BEUTZ, C.S. #333 DATE 10-15-65



SURVEYED FOR: REUBEN AND PROCTOR  
 18 SOUTH CHURCH STREET  
 DANONSO, ILLINOIS 60403  
 SURVEYED BY: DAVID R. BEUTZ  
 P.O. BOX 501  
 WYOMING, OKLAHOMA  
 (505) 678-0166

FRANTZ MFG.  
 1601 AUSTIN ROAD  
 ROSEBUCK, OKLAHOMA



