

FILED

Date: 6/7/2002 By: JP

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: _____

DOUGLAS COUNTY
SURVEYOR

RECOVERED MONUMENT LIST

PT. NO.	LDP NORTHING	LDP EASTING	DATE	DESCRIPTION
1000	19029.923	37988.140	1-07-98	FND. 5/8" IRON REBAR W/1/4" PLASTIC CAP STAMPED "O.S.H.D." 60 mm ABOVE SURFACE, GOOD CONDITION, WITNESS POST NEARBY
1001	19079.456	37990.079	1-07-98	FND. 5/8" IRON REBAR W/1/4" PLASTIC CAP STAMPED "O.S.H.D." 70 mm ABOVE SURFACE, GOOD CONDITION, WITNESS POST NEARBY
1002	19063.937	38074.262	1-08-98	FND. 5/8" IRON REBAR W/1/4" PLASTIC CAP STAMPED "O.S.H.D." 280 mm ABOVE SURFACE, GOOD CONDITION, WITNESS POST NEARBY
1003	19032.006	38073.020	1-08-98	FND. 5/8" IRON REBAR W/1/4" PLASTIC CAP STAMPED "O.S.H.D." FLUSH W/SURFACE, GOOD CONDITION, WITNESS POST NEARBY
1004	19088.402	37736.257	1-08-98	FND. 5/8" IRON REBAR 30 mm ABOVE SURFACE, GOOD CONDITION
1005	19039.798	37871.823	1-08-98	FND. 5/8" IRON REBAR W/1/4" PLASTIC CAP STAMPED "O.S.H.D." 30 mm BELOW SURFACE, GOOD CONDITION, WITNESS POST NEARBY
1006	19087.603	37834.243	1-08-98	FND. 5/8" IRON REBAR W/1/4" PLASTIC CAP STAMPED "O.S.H.D." 80 mm ABOVE SURFACE, GOOD CONDITION, WITNESS POST NEARBY
1007	19090.872	37880.541	1-08-98	FND. 5/8" IRON REBAR W/1/4" PLASTIC CAP STAMPED "O.S.H.D." 230 mm ABOVE SURFACE, GOOD CONDITION, WITNESS POST NEARBY
1008	19050.844	38407.151	1-08-98	FND. 1/2" IRON ROD 60 mm ABOVE SURFACE, GOOD CONDITION
1009	19026.542	38406.309	1-08-98	FND. 1/2" IRON ROD 100 mm BELOW SURFACE, FAIR CONDITION
1010	19107.201	38636.087	1-09-98	FND. 1/2" IRON ROD 45 mm ABOVE SURFACE, GOOD CONDITION
1011	19112.364	38633.064	1-09-98	FND. 1/2" IRON ROD 100 mm ABOVE SURFACE, GOOD CONDITION
1012	19164.314	38745.831	1-09-98	FND. 1/2" IRON ROD 210 mm ABOVE SURFACE, GOOD CONDITION
1013	19170.924	38743.640	1-09-98	FND. 1/2" IRON ROD 190 mm ABOVE SURFACE, GOOD CONDITION
1014	19256.025	39219.661	1-09-98	FND. 1/2" IRON ROD 80 mm ABOVE SURFACE, GOOD CONDITION
1015	19261.612	39217.242	1-09-98	FND. 1/2" IRON ROD 40 mm ABOVE SURFACE, GOOD CONDITION
1042	19037.847	38118.992	1-16-98	FND. 5/8" IRON REBAR W/1/4" PLASTIC CAP STAMPED "O.S.H.D." 250 mm ABOVE SURFACE, GOOD CONDITION, WITNESS POST NEARBY

RECOVERED MONUMENT LIST

PT. NO.	LDP NORTHING	LDP EASTING	DATE	DESCRIPTION & REFERENCE DOCUMENTS
1016	19264.179	39460.431	1-12-98	FND. 5/8" IRON REBAR W/1/4" PLASTIC CAP STAMPED "LS1076", FLUSH W/PAVEMENT, GOOD CONDITION (REF. SURVEY #M109-67)
1017	19201.178	39514.579	1-12-98	FND. 5/8" IRON REBAR W/1/4" PLASTIC CAP STAMPED "LS1076" 50 mm ABOVE SURFACE, GOOD CONDITION (REF. SURVEY #M109-67)
1018	19231.577	39515.069	1-12-98	FND. 1" O.D. IRON PIPE 40 mm BELOW SURFACE, GOOD CONDITION
1019	19311.102	39518.671	1-12-98	FND. 3/4" O.D. IRON PIPE 50 mm BELOW SURFACE, GOOD CONDITION (REF. SURVEY #M11-69)
1020	19274.183	39676.024	1-13-98	FND. "T" IRON FLUSH W/CONCRETE, GOOD CONDITION
1021	19219.583	39514.979	1-12-98	FND. 5/8" IRON REBAR W/1/4" PLASTIC CAP STAMPED "LS1076" 20 mm BELOW SURFACE, GOOD CONDITION
1022	19218.191	39466.219	1-13-98	FND. 5/8" IRON REBAR W/1/4" ALUM. CAP STAMPED "LS1076" FLUSH W/PAVEMENT, GOOD CONDITION (REF. SURVEY #M109-67)
1023	19202.959	39465.618	1-13-98	FND. 5/8" IRON REBAR W/1/4" ALUM. CAP STAMPED "LS1076" 50 mm ABOVE SURFACE, GOOD CONDITION (REF. SURVEY #M109-67)
1024	19192.637	39495.709	1-13-98	FND. 5/8" IRON REBAR W/1/4" PLASTIC CAP UNREADABLE, FLUSH W/PAVEMENT, GOOD CONDITION (REF. SURVEY #M109-67)
1025	19201.490	39495.776	1-13-98	FND. "T" IRON 170 mm BELOW SURFACE, GOOD CONDITION
1043	19218.489	39458.603	1-16-98	FND. 5/8" IRON REBAR W/1/4" PLASTIC CAP STAMPED "LS1076" FLUSH W/PAVEMENT, GOOD CONDITION (REF. SURVEY #M109-67)
1044	19264.050	39463.773	3-15-02	FND. 1/4" RED PLASTIC CAP STAMPED "D.A. EDWARDS LS2339" FLUSH W/AC, GOOD CONDITION (REF. SURVEY #M139-21)
1045	19218.352	39461.952	3-15-02	FND. 1/4" RED PLASTIC CAP STAMPED "D.A. EDWARDS LS2339" FLUSH W/AC, GOOD CONDITION (REF. SURVEY #M139-21)
1046	19198.688	39575.248	3-15-02	FND. 1" I.D. IRON PIPE 100 mm BELOW SURFACE, GOOD CONDITION
1047	19197.978	39593.063	3-15-02	FND. 1" I.D. IRON PIPE 150 mm BELOW SURFACE, GOOD CONDITION
1048	19195.571	39654.697	3-15-02	FND. 1" I.D. IRON PIPE 180 mm BELOW SURFACE, GOOD CONDITION
1049	19226.150	39655.878	3-15-02	FND. 1" O.D. IRON PIPE 60 mm BELOW SURFACE, GOOD CONDITION
1050	19197.979	39593.531	3-19-02	FND. 3/4" IRON ROD W/1/4" HEAD 175 mm BELOW SURFACE, GOOD CONDITION (REF. SURVEY #M14-59)
1051	19194.857	39672.999	3-19-02	FND. 1" I.D. IRON PIPE 400 mm BELOW SURFACE, GOOD CONDITION
DYH4	19253.788	39753.825	1-13-98	FND. HUB AND TACK
S8	19406.161	40346.826	1-13-98	FND. 1/4" O.D. IRON PIPE W/2 1/2" BRASS DISK STAMPED "COUNTY SURVEYORS OFFICE S8-S9-S17-S16, T22S, R5W", 60 mm ABOVE SURFACE, GOOD CONDITION

REFER TO SHEET 3

REFER TO SHEET 4

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Christine V. Blevins

OREGON
JULY 19, 1994
CHRISTINE V. BLEVINS
2669

EXPIRES 12/31/03



OREGON DEPARTMENT OF TRANSPORTATION
HORIZONTAL CONTROL, RECOVERY AND RETRACEMENT MAP

HAYHURST ROAD - SMITH RIVER ROAD

UMPQUA HIGHWAY 38

DOUGLAS COUNTY

JUNE 5, 2002

FOR ODOT REGION 3

3500 NW STEWART PKWY., ROSEBURG, OR 97470

SHEET 5 OF 8

ST. HWY. 38-010E