

Date: 11-7-2018 By: *88*

This survey consist of:

Map: St. Hwy 38-023 A-J

Narrative:

Corner Rpt: DOUGLAS COUNTY SURVEYOR

MONUMENTS FROM SHEETS 7 & 9

FD. = FOUND DRG = ODOT RIGHT OF WAY DRAWING YPC = YELLOW PLASTIC CAP DCSO = DOUGLAS COUNTY SURVEYORS OFFICE

PT. NO.	OCRS NORTHING	OCRS EASTING	ELEVATION	STATION	OFFSET (- IS LEFT)	DATE	DESCRIPTION	REFERENCE
S5	811998.09	502579.13	50.54	19+61.29	14.12	2/19/2015	FD. 5/8" IRON ROD WITH 1 1/2" ALUMINUM CAP STAMPED "OREGON STATE HWY. DIV. < PT. 5" 0.20 BELOW PAVEMENT GOOD CONDITION	ST. HWY. 38-009
S6	811584.56	503752.26	52.46	32+00.45	34.54	2/19/2015	FD. 5/8" IRON ROD WITH 1 1/2" ALUMINUM CAP STAMPED "OREGON STATE HWY. DIV. < PT.6" 0.30 FT. BELOW SURFACE GOOD CONDITION	ST. HWY. 38-009
U74	811617.63	503610.26	51.24	30+57.94	32.66	2/24/2015	FD. 2 3/4" BRASS CAP STAMPED "DOUGLAS CO. SURVEYORS OFFICE U74 1972" IN CONCRETE PEDESTAL	DCSO CONTROL U-74
101	811642.27	503571.40	52.05	30+14.57	19.77	2/19/2015	SET 5/8" X 30" IRON REBAR WITH 1 1/2" BRASS CAP STAMPED "ODOT CONTROL 101"	-
102	811881.42	502997.60	49.66	23+94.70	-15.58	2/19/2015	SET 5/8" X 30" IRON REBAR WITH 1 1/2" BRASS CAP STAMPED "ODOT CONTROL 102"	-
112	811587.67	503403.77	44.07	-	-	6/28/2016	SET 5/8" X 30" IRON REBAR WITH 1 1/2" ALUMINUM CAP STAMPED "ODOT CONTROL 112"	-
113	811626.64	503165.24	33.28	-	-	6/28/2016	SET 5/8" X 30" IRON REBAR WITH 1 1/2" ALUMINUM CAP STAMPED "ODOT CONTROL 113"	-
114	811692.78	502921.03	32.00	-	-	6/28/2016	SET 5/8" X 30" IRON REBAR WITH 1 1/2" ALUMINUM CAP STAMPED "ODOT CONTROL 114"	-
500	811867.48	502919.14	49.53	23+25.40	23.76	2/25/2015	FD. STEEL SPIKE IN PAVEMENT	UNRECORDED
BURG	811811.49	502574.27	33.69	-	-	2/17/2015	SET 5/8" IRON REBAR WITH 1 1/2" BRASS CAP STAMPED "ODOT CONTROL BURG" STABILIZED IN CONCRETE	-
1028	811998.06	502500.57	-	18+87.25	40.37	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.10 FT ABOVE SURFACE GOOD CONDITION	RM4-17
1029	811939.92	502665.85	-	20+62.45	40.00	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.20 FT ABOVE SURFACE GOOD CONDITION	RM4-17
1030	811914.87	502736.68	-	21+37.58	39.98	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.20 FT ABOVE SURFACE GOOD CONDITION	RM4-17
1031	811881.43	502831.13	-	22+37.78	39.98	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.40 FT ABOVE SURFACE GOOD CONDITION	RM4-17
1032	811839.52	502949.22	-	23+63.08	40.08	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.30 FT ABOVE SURFACE GOOD CONDITION	RM4-17
1033	811831.20	502972.75	-	23+88.04	40.06	3/18/2015	FD. PK NAIL IN PAVEMENT NEAR POST OFFICE	RM4-17
1034	811805.67	503043.44	-	24+63.20	40.53	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.50 FT ABOVE SURFACE GOOD CONDITION	RM4-17
1035	811740.65	503228.82	-	26+59.65	39.95	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.40 FT ABOVE SURFACE GOOD CONDITION	RM4-17
1036	811677.47	503407.08	-	28+48.77	40.01	3/17/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.30 FT ABOVE SURFACE GOOD CONDITION	RM4-17
1037	811668.71	503431.94	-	28+75.13	39.97	3/17/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.10 FT BELOW SURFACE GOOD CONDITION	RM4-17
1038	811642.92	503504.67	-	29+52.27	40.01	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC ROD THROUGH CAP NOT READABLE 0.10 FT BELOW SURFACE GOOD CONDITION	RM4-17
1039	811619.80	503575.61	-	30+24.86	40.07	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1040	811568.02	503605.26	-	30+65.70	81.87	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1042	811718.34	503531.38	-	29+52.33	-40.01	3/18/2015	FD. 3/4" O.D. IRON PIPE 0.30 FT ABOVE SURFACE FAIR CONDITION- CARSONITE POST NEARBY	DRG 2C-1-16
1043	811566.29	503655.25	-	31+12.14	71.46	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1044	811564.13	503705.21	-	31+59.24	63.09	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.10 FT ABOVE SURFACE GOOD CONDITION	RM4-17
1045	811573.49	503705.50	-	31+57.76	53.85	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1046	811572.66	503755.38	-	32+05.33	45.76	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.20 FT ABOVE SURFACE GOOD CONDITION	RM4-17
1047	811571.97	503797.48	-	32+45.86	40.20	11/13/2017	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1048	811561.33	503905.22	-	33+51.19	40.28	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH GRAVEL GOOD CONDITION	RM4-17
1049	811559.04	503955.23	-	33+99.88	40.37	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.1 FT. ABOVE SURFACE GOOD CONDITION	RM4-17
1050	811559.37	504155.22	-	35+98.55	40.43	3/18/2015	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1052	811881.01	502284.81	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.6 FT. ABOVE SURFACE GOOD CONDITION	RM4-17
1053	811905.34	502393.66	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1054	811856.81	502381.20	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1055	811885.81	502461.72	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1056	811883.90	502467.73	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1057	811837.55	502446.27	-	-	-	8/1/2016	FD. 5/8" IRON REBAR BENT SOUTHERLY, TIED WHERE ROD ENTERS GROUND, FLUSH WITH SURFACE POOR CONDITION	RM4-17
1058	811835.81	502453.86	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.2 FT. ABOVE SURFACE GOOD CONDITION	RM4-17
1059	811835.60	502635.92	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1060	811806.65	502705.64	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.3 FT. ABOVE SURFACE GOOD CONDITION	RM4-17
1061	811758.58	502691.80	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.6 FT. ABOVE SURFACE GOOD CONDITION	RM4-17
1062	811775.89	502800.82	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.6 FT. ABOVE SURFACE GOOD CONDITION	RM4-17
1063	811737.15	502919.77	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.6 FT. ABOVE SURFACE GOOD CONDITION	RM4-17
1064	811729.38	502943.57	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.2 FT. ABOVE SURFACE GOOD CONDITION	RM4-17
1065	811727.61	502949.01	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.3 FT. ABOVE SURFACE GOOD CONDITION	RM4-17
1066	811681.27	502929.79	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.3 FT. ABOVE SURFACE GOOD CONDITION	RM4-17
1067	811680.07	502933.63	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.3 FT. ABOVE SURFACE GOOD CONDITION	RM4-17
1068	811660.21	503001.75	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.2 FT. ABOVE SURFACE GOOD CONDITION	RM4-17
1069	811658.05	503010.12	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.2 FT. ABOVE SURFACE GOOD CONDITION	RM4-17
1070	811708.27	503015.51	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1071	811706.51	503022.28	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1072	811660.63	503204.78	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1073	811617.46	503171.58	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.3 FT. ABOVE SURFACE GOOD CONDITION	RM4-17
1074	811559.68	503154.90	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1075	811596.75	503254.17	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1076	811628.26	503381.62	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1077	811578.37	503379.46	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1078	811576.16	503430.61	-	-	-	8/1/2016	FD. BENT IRON ROD IN 15" CONCRETE BLOCK, TIED WHERE ROD GOES INTO CONCRETE BLOCK, POOR CONDITION	RM4-17
1079	811576.71	503430.26	-	-	-	8/1/2016	FD. 2" DRIVE LINE WITH 1" DIAMETER INTERNAL SPLINE, 0.9 FT ABOVE SURFACE FAIR CONDITION	RM4-17
1080	811627.25	503406.23	-	-	-	8/1/2016	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" FLUSH WITH SURFACE GOOD CONDITION	RM4-17
1081	811626.21	503431.31	-	-	-	8/1/2016	FD. 5/8" IRON REBAR LEANS EASTERLY, TIED WHERE ROD ENTERS GROUND, FLUSH WITH SURFACE FAIR CONDITION	RM4-17
1091	811640.11	504205.55	-	36+49.36	-40.01	11/13/2017	FD. 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "AA SURVEYING" 0.2 FT. ABOVE SURFACE GOOD CONDITION	M116-80

REGISTERED PROFESSIONAL LAND SURVEYOR

Marshall R Wagstaff

OREGON
JANUARY 9, 2001
MARSHALL R. WAGSTAFF
49476LS

RENEWS: JUNE 30, 2020

OREGON DEPARTMENT OF TRANSPORTATION

HORIZONTAL CONTROL, RECOVERY AND RETRACEMENT MAP
OR38: UMPQUA RIVER (SCOTTSBURG) BRIDGE REPLACEMENT
UMPQUA HIGHWAY MP. 15.9 - 17.1

DOUGLAS COUNTY
FILE: S_K18578_CRR_01.DGN :: CRR

FOR ODOT REGION 3
3500 NW STEWART PKWY.
ROSEBURG, OR. 97470



NOVEMBER 2, 2018

SHEET 8 OF 10