

**COUNTY SURVEYORS FILE DATA
DO NOT REMOVE FROM OFFICE**

FILED
Date: 4-29-2002 By: JC
This survey consists of:
Map: St. Hwy 42-007A-H
Narrative: _____
Corner Rpt: _____

**DOUGLAS COUNTY
SURVEYOR**

POINT ID	LDP NORTHING	LDP EASTING	DESCRIPTION
116	167875.380	374799.861	SET 16 mm X 762 mm IRON REBAR WITH A 38 mm BRASS CAP STAMPED "ODOT CONTROL 116" 50 mm BELOW SURFACE.
117	168026.319	374958.196	SET 16 mm X 762 mm IRON REBAR WITH A 38 mm BRASS CAP STAMPED "ODOT CONTROL 117" FLUSH WITH SURFACE.
118	168235.653	375193.466	SET 16 mm X 762 mm IRON REBAR WITH A 38 mm BRASS CAP STAMPED "ODOT CONTROL 118" 50 mm BELOW SURFACE.
124	167146.666	374007.334	FOUND 3" BRASS DISK SET IN CONC. BRIDGE IMPACT PANEL STAMPED "DOUGLAS CO. SURVEYORS OFFICE P247 RM2 1978" IN GOOD CONDITION.
500	167029.488	373884.726	FOUND 3" BRASS DISK STAMPED "DOUGLAS CO. SURVEYORS OFFICE P247 RM1 1978" SET IN CONC. BRIDGE SIDEWALK.
1109	166997.552	373765.913	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DIV." IN FAIR CONDITION.
1110	166947.470	373800.606	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DIV." 30 mm ABOVE SURFACE IN FAIR CONDITION.
1111	167163.728	373994.610	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY." 20 mm ABOVE SURFACE IN FAIR CONDITION.
1113	167739.957	374636.951	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DEPT." FLUSH WITH SURFACE IN GOOD CONDITION (STA. 1267+80.00 P.O.T., 100.00 FT. LT.)
1114	167694.641	374680.013	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DEPT. R/W 1267+80" FLUSH WITH SURFACE IN GOOD CONDITION. ODOT R/W STA. 1267+80, 105 FT. RT. (ODOT R/W DRG. NO. *9B-7-5)
1115	168093.777	375004.475	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DIV. 1284+54.02 110.0" FLUSH WITH SURFACE IN FAIR CONDITION.
1116	168045.217	375050.685	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DIV. 1284+54.02 110" FLUSH WITH SURFACE IN GOOD CONDITION (STA. 1284+54.02 P.S., 110.00 FT. RT.)
1117	168184.552	375192.963	FOUND 5/8" IRON REBAR BADLY BENT IN POOR CONDITION. TIED WHERE ROD ENTERS THE GROUND. (REF. SURVEY *1992-0018)
1119	168212.721	375230.815	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "LANG SURVEYING" 70 mm BELOW SURFACE. (REF. SURVEY *128-28)
1121	168235.981	375265.640	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "LANG SURVEYING" 110 mm ABOVE SURFACE IN GOOD CONDITION. (REF. SURVEY *1992-0018)
1122	168253.734	375294.627	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "LANG SURVEYING" 200 mm BELOW SURFACE IN GOOD CONDITION. (REF. SURVEY *1992-0019)
1124	168278.728	375338.916	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "LANG SURVEYING" FLUSH WITH SURFACE IN GOOD CONDITION. (REF. SURVEY *1998-0106)
1125	168287.236	375354.931	FOUND 5/8" IRON ROD 70 mm ABOVE SURFACE IN POOR CONDITION. ROD IS BENT AND CAP IS DESTROYED, TIED WHERE IT ENTERS THE GROUND. (REF. SURVEY *1992-0019)
1126	168282.560	375357.399	FOUND 5/8" IRON ROD FLUSH WITH SURFACE. ROD IS SLIGHTLY BENT IN POOR TO FAIR CONDITION, CAP IS DESTROYED. (REF. SURVEY *1998-0106)
1127	168276.939	375360.315	FOUND 1/2" IRON ROD 40 mm ABOVE SURFACE IN GOOD CONDITION. (REF. SURVEY *1992-0019)
1128	168295.327	375370.352	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "LANG SURVEYING" 40 mm ABOVE SURFACE IN GOOD CONDITION. (REF. SURVEY *1998-0106)
1129	168300.597	375380.648	FOUND 5/8" IRON REBAR 410 mm BELOW SURFACE IN GOOD CONDITION. (REF. SURVEY *M101-34)
1130	168316.862	375413.037	FOUND 5/8" IRON REBAR 160 mm BELOW SURFACE IN GOOD CONDITION. CAP DESTROYED. (REF. SURVEY *M101-34)
1133	168223.067	375245.905	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "LANG SURVEYING" FLUSH WITH SURFACE IN GOOD CONDITION. (REF. SURVEY *128-28)
1134	168256.270	375192.217	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DIV. 1292+54.02 P.S.C. 110" FLUSH WITH SURFACE IN GOOD CONDITION.
1136	168241.047	375171.518	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "BTS ENG SURV." 400 mm BELOW SURFACE IN GOOD CONDITION. (REF. SURVEY *120-19)
1138	168321.364	375296.330	FOUND 5/8" IRON REBAR FLUSH WITH SURFACE IN POOR CONDITION. REBAR BENT OVER, TIED WHERE REBAR ENTERS GROUND. (REF. SURVEY *120-19)
1139	168329.592	375311.371	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. 1297" 200 mm BELOW SURFACE IN FAIR TO POOR CONDITION. ABOUT A THIRD OF CAP IS DAMAGED AND UNREADABLE.
1140	168362.344	375381.365	FOUND NAIL IN CONC. SLAB FLUSH WITH SURFACE IN GOOD CONDITION. (REF. SURVEY *M76-63)
1179	167931.340	375137.824	FOUND 2 1/4" BRASS DISK STAMPED "COUNTY SURVEYORS OFFICE 1962 T28S R6W S10 S11 S15 S14" ON A GALVANIZE PIPE 300 mm ABOVE THE SURFACE IN GOOD CONDITION.
P247	167124.098	374022.758	FOUND 3" BRASS DISK STAMPED "STATE HIGHWAY DEPARTMENT BENCH MARK P247 ELEVATION ABOVE MEAN SEA LEVEL FEET RESET" SET FLUSH IN CONC. BRIDGE SIDEWALK

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Christine V. Blewins

OREGON
JULY 19, 1994
CHRISTINE V. BLEWINS
2669

EXPIRES: DEC. 31, 2003



1 METER = 3937 U.S. FEET / 1200
TO CONVERT A METRIC DISTANCE DIVIDE BY 0.30480061

**OREGON DEPARTMENT OF TRANSPORTATION
HORIZONTAL CONTROL, RECOVERY,
AND RETRACEMENT MAP
WINSTON - INTERSTATE 5
COOS BAY - ROSEBURG HWY.
DOUGLAS COUNTY
3500 STEWART PARKWAY, SUITE 140
ROSEBURG, OREGON 97470**

APRIL 23, 2002
PROJECT KEY *09841

SHEET 6 OF 8

ST. HWY. 42-007F