

COUNTY SURVEYORS FILE DATA

DO NOT REMOVE FROM OFFICE

POINT ID	LDP NORTHING	LDP EASTING	DESCRIPTION
6	168414.038	375494.033	FOUND 38 mm ALUM. CAP STAMPED "ODOT HORIZ. CONTROL 6" FLUSH WITH SURFACE IN GOOD CONDITION. (REF. SURVEY #129-21)
7	168348.760	375467.375	FOUND 38 mm ALUM. CAP STAMPED "ODOT HORIZ. CONTROL 7" FLUSH WITH ASPHALT CONC. IN GOOD CONDITION. (REF. SURVEY #129-21)
11	169127.797	376814.511	FOUND 38 mm BRASS CAP STAMPED "ODOT CONTROL 11" 50 mm BELOW SURFACE IN GOOD CONDITION. ORANGE CARSONITE POST NEARBY. (REF. SURVEY *ST. HWY. IS-006, A-L)
12	169087.101	376748.236	FOUND 38 mm BRASS CAP STAMPED "ODOT CONTROL 12" 50 mm BELOW SURFACE IN GOOD CONDITION. ORANGE CARSONITE WITNESS POST NEARBY. (REF. SURVEY *ST. HWY. IS-006, A-L)
119	168436.192	375557.725	SET 16 mm X 762 mm IRON REBAR WITH A 38 mm BRASS CAP STAMPED "ODOT CONTROL 119". SET IN ASPHALT CONC. WALK FLUSH WITH SURFACE.
120	168436.825	375638.534	SET 16 mm X 762 mm IRON REBAR WITH A 38 mm BRASS CAP STAMPED "ODOT CONTROL 120" FLUSH WITH SURFACE.
121	168555.483	375813.861	SET 16 mm X 762 mm IRON REBAR WITH A 38 mm BRASS CAP STAMPED "ODOT CONTROL 121" 20 mm BELOW SURFACE.
122	168656.580	376094.998	SET 16 mm X 762 mm IRON REBAR WITH A 38 mm BRASS CAP STAMPED "ODOT CONTROL 122" 50 mm BELOW SURFACE.
123	168930.966	376503.147	SET 16 mm X 762 mm IRON REBAR WITH A 38 mm BRASS CAP STAMPED "ODOT CONTROL 123" FLUSH WITH SURFACE.
1132	168350.110	375480.616	FOUND RAIL ROAD SPIKE IN ASPHALT CONC. IN GOOD CONDITION.
1141	168378.029	375433.803	FOUND 1 1/2" UNREADABLE ALUM. CAP WITH ROD BENT OVER. TIED WHERE ROD ENTERS GROUND. (EQUATION STATION 1301+29.44 P.O.T. AH. = 1301+26.31 P.T. BK.)
1143	168431.921	375516.122	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "I.E. ENG." 30 mm ABOVE SURFACE IN GOOD CONDITION. (REF. SURVEY #1997-0112)
1148	168478.772	375465.794	FOUND 5/8" IRON REBAR 150 mm BELOW SURFACE FAIR TO POOR CONDITION. ROD LEANS A LITTLE. (REF. SURVEY *M66-17)
1149	168504.396	375463.312	FOUND 5/8" IRON REBAR 20 mm BELOW SURFACE IN GOOD CONDITION. (REF. SURVEY *M62-40)
1151	168556.133	375458.090	FOUND 5/8" IRON REBAR 20 mm BELOW SURFACE IN GOOD CONDITION. (REF. SURVEY *M62-40)
1152	168591.389	375454.562	FOUND 1 1/2" ANGLE IRON 100 mm BELOW SURFACE IN GOOD CONDITION.
1153	168562.500	375457.398	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "BTS ENG SURV." FLUSH WITH SURFACE IN GOOD CONDITION. (REF. SURVEY *M63-64)
1154	168415.014	375490.308	FOUND 1 1/4" PLASTIC CAP STAMPED "I.E. ENG." FLUSH WITH SURFACE IN GOOD CONDITION. (REF. SURVEY #1997-0112)
1155	168535.716	375478.317	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "I.E. ENG." 100 mm ABOVE SURFACE IN GOOD CONDITION. (REF. SURVEY #1997-0112)
1156	168447.991	375559.301	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DIV. 1306 95.0" 400 mm BELOW SURFACE IN GOOD CONDITION. POST AND PADDLE NEARBY 1306+00, 95.0 FT. LT.
1157	168478.381	375613.897	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "I.E. ENG." 100 mm ABOVE SURFACE IN GOOD CONDITION. (REF. SURVEY #1997-0112)
1158	168577.760	375792.567	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "AA SURVEYING INC." 30 mm ABOVE SURFACE IN GOOD CONDITION. (REF. SURVEY #100-45)
1159	168582.825	375802.689	FOUND 5/8" IRON ROD WITH A 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DIV. R/W EQUA" 150 mm ABOVE SURFACE IN GOOD CONDITION. POST AND PADDLE BOARD NEARBY MARKED "EQ SHRW POT 1315+11.83 BK. POT 1315+00 AH. R/W 140".
1160	168217.752	375499.034	FOUND 5/8" IRON ROD WITH 1 1/4" PLASTIC CAP STAMPED "BENTZ SUR. INC." 40 mm ABOVE SURFACE IN GOOD CONDITION. (REF. SURVEY 1990-0020)
1168	168398.776	375583.320	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DIV." FLUSH WITH SURFACE IN GOOD CONDITION. POST AND PADDLE BOARD SHRW 1306+00, 85 FT. RT.
1169	168420.960	375636.004	FOUND 5/8" IRON REBAR WITH A 1 1/4" YELLOW PLASTIC CAP STAMPED "ARTMAN RLS 2268" 100 mm ABOVE SURFACE IN GOOD CONDITION. (REF. SURVEY #114-53)
1170	168428.074	375652.880	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "ARTMAN RLS 2268" FLUSH WITH ASPHALT CONC. PAVEMENT IN GOOD CONDITION. (REF. SURVEY #M114-53)
1171	168502.486	375829.405	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DIV." FLUSH WITH SURFACE IN GOOD CONDITION. (R/W STATION 1314+75, 135 FT. RT.)
1172	168614.675	375470.447	FOUND 5/8" IRON REBAR WITH A 1 1/4" YELLOW PLASTIC CAP STAMPED "I.E. ENG." 170 mm ABOVE SURFACE IN GOOD CONDITION. (REF. SURVEY #M1997-0112)
1173	168632.907	375946.219	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DIV." 80 mm ABOVE SURFACE IN GOOD CONDITION. CAP IS LOOSE, POST NEARBY R/W STATION 1320+00, 50 FT. LT.
1174	168678.416	376156.523	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DEPT. 1313+50 175.0" 150 mm BELOW SURFACE IN GOOD CONDITION. POST AND BOARD NEARBY MARKED "SHRW 1313+50 RW 175".
1175	168713.273	376181.928	FOUND 5/8" IRON ROD WITH 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DEPT. 1312+20 100.0" 160 mm ABOVE SURFACE IN GOOD CONDITION. POST AND PADDLE NEARBY SHRW 1312+20 RW 120
1176	168913.949	376487.987	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "O.S.H.D. R/W" FLUSH WITH SURFACE IN GOOD CONDITION. POST AND PADDLE MARKED "SHRW 1300+20 70.0 LT."
1177	168922.796	376496.852	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "O.S.H.D. R/W" 70 mm BELOW SURFACE IN GOOD CONDITION. POST AND PADDLE BOARD NEARBY MARKED "SHRW 1299+80 60.0 LT."
GS3	168865.885	376335.509	FOUND 38 mm ALUM. CAP STAMPED "ODOT HORIZ. CONTROL 3" FLUSH WITH SURFACE IN GOOD CONDITION. (REF. SURVEY #129-14)
ISLAND	168767.653	376168.724	FOUND 76 mm BRASS CAP STAMPED "OREGON STATE HIGHWAY DIVISION DO NOT DISTURB ISLAND" SET IN CONC. ISLAND. (REF. SURVEY #129-14)
K675	168619.298	375937.560	FOUND 3" BRASS CAP IN CONC. SIDEWALK STAMPED "OREGON STATE HIGHWAY DIV. BENCH MARK K675 1978" IN GOOD CONDITION.

FILED
Date: 4-29-2002 By: JC
This survey consists of:
Map: ST HWY 42-007 A-W
Narrative:
Corner Rpt: _____

DOUGLAS COUNTY
SURVEYOR

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Christine V. Blavins

OREGON
JULY 19, 1994
CHRISTINE V. BLAVINS
2669

EXPIRES: DEC. 31, 2003



1 METER = 3937 U.S. FEET / 1200
TO CONVERT A METRIC DISTANCE DIVIDE BY 0.30480061

OREGON DEPARTMENT OF TRANSPORTATION
HORIZONTAL CONTROL, RECOVERY,
AND RETRACEMENT MAP
WINSTON - INTERSTATE 5
COOS BAY - ROSEBURG HWY.
DOUGLAS COUNTY
3500 STEWART PARKWAY, SUITE 140
ROSEBURG, OREGON 97470

APRIL 23, 2002
PROJECT KEY #09841

SHEET 8 OF 8

ST. HWY. 42-007H