

RECOVERED MONUMENT LIST

PT. NO.	LDP NORTHING	LDP EASTING	STATION	OFFSET	DATE	DESCRIPTION & REFERENCE DOCUMENTS
1000	606021.259	4162720.697	2255+54.85	-124.96	5-13-03	FND. 5/8" I. ROD 1" ABOVE SURFACE, GOOD CONDITION (ODOT DRG. NO. 7B-7-10)
1001	606125.112	4162493.376	2255+54.93	124.96	5-12-03	FND. 5/8" I. ROD FLUSH W/SURFACE, GOOD CONDITION, PADDLE BOARD NEARBY MARKED "SHRW PT 2255+53.31 125" (ODOT DRG. NO. 7B-7-10)
1002	604887.195	4162202.082	2268+01.87	-124.91	5-12-03	FND. 5/8" I. ROD 1" BELOW SURFACE, GOOD CONDITION, PADDLE BOARD NEARBY MARKED "SHRW 2268+00 125 LT" (ODOT R/W DRG. NO. 7B-7-10)
1003	604694.713	4162141.861	2270+01.96	-150.18	5-12-03	FND. 5/8" I. ROD, GOOD CONDITION, PADDLE BOARD NEARBY MARKED "SHRW 2270+00 150 LT" (ODOT R/W DRG. NO. 7B-7-10)
1004	604809.478	4161891.439	"C1"2270+08.71	73.04	5-12-03	FND. 5/8" I. ROD 2 1/2" ABOVE SURFACE, GOOD CONDITION, PADDLE BOARD NEARBY MARKED "SHRW 2270+00 125 RT" (ODOT R/W DRG. NO. 7B-7-10)
1005	604322.039	4161971.256	2274+11.83	-150.00	5-12-03	FND. 5/8" I. ROD 2 1/2" ABOVE SURFACE, GOOD CONDITION, PADDLE BOARD NEARBY MARKED "SHRW PS 2274+09.68 150 LT" (ODOT R/W DRG. NO. 7B-7-10)
1006	602516.204	4161590.427	"OS"2275+08.64	29.81	5-8-03	FND. 5/8" I. ROD 10" BELOW SURFACE, GOOD CONDITION (REF. #M39-70)
1007	597414.091	4161173.449	2345+00.00	125.00	5-7-03	FND. 5/8" I. ROD 1" ABOVE CONC., GOOD CONDITION, WOOD POST NEARBY (ODOT R/W DRG. NO. 7B-7-10)
1008	596928.078	4161057.755	2349+99.60	126.07	5-7-03	FND. 2 3/4" BRASS DISK SET IN CONC. STAMPED "STATE HIGHWAY DEPARTMENT REFERENCE", FLUSH W/ SURFACE, GOOD CONDITION, WOOD POST NEARBY (ODOT R/W DRG. NO. 7B-7-10)
1009	596441.424	4160944.352	2354+99.29	124.76	5-7-03	FND. 5/8" I. ROD SET IN CONC. 1/2" ABOVE CONC., WOOD POST NEARBY, GOOD CONDITION (ODOT R/W DRG. NO. 7B-7-10)
1010	595954.416	4160828.512	2359+99.88	125.74	5-7-03	FND. 2 3/4" BRASS DISK SET IN CONC. STAMPED "STATE HIGHWAY DEPARTMENT REFERENCE", FLUSH W/ SURFACE, GOOD CONDITION (ODOT R/W DRG. NO. 7B-7-10)
1011	597901.107	4161287.383	2339+99.84	125.88	5-7-03	FND. 2 3/4" BRASS DISK SET IN CONC. STAMPED "OREGON HIGHWAY DEPARTMENT REFERENCE", GOOD CONDITION, WOOD POST NEARBY (ODOT R/W DRG. NO. 7B-7-10)
1012	601418.313	4161308.609	N/A	N/A	5-13-03	FND. 2 1/2" BRASS DISK ON 1 1/4" O.D. I. PIPE STAMPED "COUNTY SURVEYORS OFFICE T26S R6W W.C. N.W. COR. D.L.C. 53 1954", 10" ABOVE SURFACE, GOOD CONDITION
1013	598330.864	4161112.352	N/A	N/A	5-7-03	FND. 5/8" I. REBAR 3 1/4" ABOVE SURFACE, GOOD CONDITION, BELIEVED TO BE 1/4 CORNER SEC. 25 & SEC. 36
1014	604617.562	4161691.359	"C1"2273+28.02	60.00	5-12-03	FND. 5/8" I. ROD 2" ABOVE SURFACE, GOOD CONDITION, PADDLE BOARD NEARBY MARKED "SHRW 'C' PT 2273+27.64 60" (ODOT R/W DRG. NO. 7B-7-10)
1015	604695.952	4161793.366	"C1"2271+88.16	74.89	5-12-03	FND. 5/8" I. ROD 2" ABOVE SURFACE, BENT BADLY TO NW, TIED WHERE ROD ENTERS GROUND, PADDLE BOARD NEARBY MARKED "SHRW 'C' PCS 2271+87.64 75" (ODOT R/W DRG. NO. 7B-7-10)
1016	604753.031	4161851.137	"C1"2270+88.49	75.06	5-12-03	FND. 5/8" I. ROD BLUSH W/SURFACE, GOOD CONDITION, STINGER NEARBY, PADDLE ON GROUND MARKED 'SHRW 'C' PSC 2270+88.00 75" (ODOT R/W DRG. NO. 7B-7-10)
1017	606250.365	4162824.166	2253+04.81	-124.69	5-13-03	FND. 5/8" I. ROD 2" ABOVE SURFACE, GOOD CONDITION (ODOT R/W DRG. NO. 7B-7-10)
1018	606351.540	4162595.956	2253+05.00	124.94	5-12-03	FND. 5/8" I. ROD 1" ABOVE SURFACE, GOOD CONDITION, PADDLE BOARD NEARBY MARKED "SHRW L2 2253+03.31 125" (ODOT R/W DRG. NO. 7B-7-10)
1019	606902.735	4162822.439	2247+02.43	126.10	5-13-03	FND. 5/8" I. ROD 4" ABOVE SURFACE, GOOD CONDITION, PADDLE BOARD NEARBY MARKED "SHRW 2247+00 125" (ODOT R/W DRG. NO. 7B-7-10)
1020	608372.495	4163247.287	2231+52.77	151.42	5-13-03	FND. 5/8" I. ROD 3" ABOVE SURFACE, GOOD CONDITION, PADDLE NEARBY MARKED "SHRW 2231+50 150 RT" (ODOT R/W DRG. NO. 7B-7-10)
1021	609193.466	4163358.024	2223+12.74	200.76	5-13-03	FND. 5/8" I. ROD 2 1/2" ABOVE SURFACE, GOOD CONDITION, PADDLE BOARD NEARBY MARKED "SHRW PSC 2223+09.42 200 RT" (ODOT R/W DRG. NO. 8B-26-7)
1022	600417.415	4161972.265	"OS"2301+38.11	-30.60	5-8-03	FND. 5/8" I. ROD W/1 1/2" ALUM. CAP SET 3'5 1/2" BELOW SURFACE IN PLASTIC PIPE
1025	601207.018	4161748.873	"OS"2288+27.38	26.87	5-7-03	FND. 1" O.D. I. PIPE 6" BELOW SURFACE, BENT SLIGHTLY TO WEST, FAIR CONDITION (REF. #M41-48)
1026	601331.239	4161730.969	"OS"2287+01.91	30.00	5-7-03	FND. 1 1/2" O.D. PIPE 9" BELOW SURFACE, GOOD CONDITION (REF. #M41-48)
1028	602558.154	4161645.792	"OS"2274+73.14	-30.09	5-8-03	FND. 5/8" I. REBAR 2" ABOVE SURFACE, GOOD CONDITION
1029	602733.367	4161675.449	"OS"2272+76.77	-29.92	5-8-03	FND. 5/8" I. ROD 2 1/2" BELOW PAVEMENT, POOR CONDITION, BENT TO WEST, TIED WHERE ROD ENTERS GROUND
1030	603155.209	4161874.840	"OS"2268+10.18	-30.01	5-8-03	FND. 1 1/4" PLASTIC CAP STAMPED "LANDMARK PLS 2287", GOOD CONDITION (REF. #M132-8)
1031	603223.007	4161906.865	"OS"2267+35.20	-30.00	5-8-03	FND. 1 1/4" PLASTIC CAP STAMPED "LANDMARK PLS 2287" 1" ABOVE SURFACE, GOOD CONDITION (REF. #M132-8)
1032	603215.211	4161938.986	N/A	N/A	5-8-03	FND. 1 1/4" PLASTIC CAP STAMPED "LANDMARK PLS 2287" 3/4" ABOVE SURFACE, GOOD CONDITION (REF. #M132-8)
1033	603918.865	4162235.623	"OS"2259+65.59	-30.00	5-8-03	FND. 1 1/4" I.D. I. PIPE 21" BELOW SURFACE, GOOD CONDITION (REF. #M39-70)
1034	603903.145	4162285.396	N/A	N/A	5-8-03	FND. 5/8" I. REBAR W/1 1/4" PLASTIC CAP, CAP IN POOR COND., 6" ABOVE SURFACE, GOOD CONDITION (REF. #M90-64)
1035	604194.554	4162590.631	"CR"12+24.51	35.13	5-8-03	FND. 3/4" I. ROD 3" ABOVE SURFACE, GOOD CONDITON, WOOD POST NEARBY MARKED "CRRW"

FILED
 Date: 4-15-2004 By: JC
 This survey consists of:
 Map: ST HWY 15-016 A-B
 Narrative:
 Corner Pkt:
 DOUGLAS COUNTY SURVEYOR

REGISTERED PROFESSIONAL LAND SURVEYOR
 Christine V. Blevins
 OREGON JULY 19, 1994
 CHRISTINE V. BLEVINS 2669
 EXPIRES: DEC. 31, 2005

OREGON DEPARTMENT OF TRANSPORTATION
 HORIZONTAL CONTROL, RECOVERY AND RETRACEMENT MAP
 I-5: EXIT 129 / N. UMPQUA RIVER (WINCHESTER) BRIDGES
 INTERSTATE 5 AND OAKLAND-SHADY HIGHWAY
 DOUGLAS COUNTY
 MARCH 24, 2004 FOR ODOT REGION 3
 3500 NW STEWART PARKWAY ROSEBURG, OR 97470
 SHEET 4 OF 11