



383	496444.0117	4166345.2804	IRON PIPE, SEARCHED FOR NOT FOUND	7B-22-19
384	496574.8774	4166132.2683	IRON PIPE, SEARCHED FOR NOT FOUND	7B-22-19
385	496601.0505	4166089.6658	147+00 175' RT, A 5/8 INCH SMOOTH IRON ROD IN MIDDLE OF GRAVEL LANE, 1.0 BELOW SURFACE, LYING ON SIDE	7B-22-19
386	496393.2301	4165966.6092	IRON PIPE, SEARCHED FOR NOT FOUND	7B-22-19
387	496575.9926	4166430.1582	IRON PIPE, SEARCHED FOR NOT FOUND	7B-22-19
388	496716.3475	4166223.2754	145+37.42 125' RT, A 5/8 INCH SMOOTH IRON ROD IN CONCRETE, CONCRETE IS BROKEN AND DISTURBED IN ROW FENCE, 0.2' BELOW SURFACE	7B-22-19
389	497120.4775	4166552.3363	IRON PIPE, SEARCHED FOR NOT FOUND	7B-22-19
390	496946.3300	4166731.7037	IRON PIPE, SEARCHED FOR NOT FOUND	7B-22-19
391	497213.9396	4167017.0348	136+37.42 125' LT, A "T-POST" IN CONCRETE, 1.0 EAST OF ROW FENCE	7B-22-19
392	497400.1751	4166850.2526	FD 4"x 4" WOODEN POST, NO PIPE	7B-22-19
393	497825.4165	4167325.0937	4"x 4" WOODEN POST, NO PIPE	7B-22-19
424	497639.1809	4167491.8759	130+00.0 125' LT, A 5/8 INCH SMOOTH IRON ROD, 0.6' EAST OF ROW FENCE POST, 0.7' NE OF 4x4 WOODEN POST, 0.1 ABOVE GROUND	7B-22-19
653	496454.3340	4166124.6916	1 1/2 INCH ALUMINUM CAP ON IRON ROD, FLUSH WITH GROUND, MARKED "ODOT HORIZ. CONTROL 33"	7B-22-19
654	496451.8209	4166238.1923	1 1/2 INCH ALUMINUM CAP ON IRON ROD, FLUSH WITH GROUND, MARKED "ODOD HORIZ. CONTROL 32"	129-39
655	497033.6614	4166642.4508	A 2 3/4 INCH BRASS DISC IN CONCRETE, 0.5' BELOW SURFACE MARKED "STATE HWY DEPARTMENT BM NO Y565 1958 ELEVATION FEET"	129-39
656	497307.4672	4166934.0945	A 2 3/4 INCH BRASS DISC IN CONCRETE, 0.4' BELOW SURFACE MARKED "STATE HWY DEPART. BM NO X565 1958 ELEVATION FEET"	129-39
657	497731.2434	4167407.3064	1 1/2 INCH ALUMINUM CAP ON IRON ROD FLUSH WITH SURFACE AT 130+00 POT., MARKED "OREG. STATE HWY DIV."	129-39

LEGEND

- INDICATES FOUND ODOT MONUMENT
- INDICATES FOUND MONUMENT FROM PUBLIC SURVEY
- INDICATES MONUMENT SEARCHED FOR BUT NOT FOUND

REGISTERED PROFESSIONAL LAND SURVEYOR
 H.M.
 OREGON JAN. 21, 1998 HARMON E. McLENDON 2537
 RECORDED 12/31/04

MONUMENT RECOVERY SURVEY
 NW1/4 SEC. 5, NE1/4 SEC. 6, T30S, R5W, W.M.
 DOUGLAS COUNTY, OREGON

OREGON DEPARTMENT OF TRANSPORTATION

SCALE: 1"=100'
 DATE: JULY 2004
 JOB NO. 863-60

anderson perry
 associates, inc.
 ENGINEERING SURVEYING MATERIALS TESTING
 LA GRANDE, OR. WALLA WALLA, WA.

SHEET **6/8**